

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

C/S  
Op

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88240

DISTRICT II  
811 South First, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, New Mexico 87505

WELL API NO. 30-015-03026
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1266
7. Lease Name or Unit Agreement Name G J West Coop Unit
8. Well No. 30
9. Pool name or Wildcat Grbg Jackson SR Q Grbg SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3568 GR

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).	
1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator MACK ENERGY CORPORATION	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960 (505) 748-1288	
4. Well Location Unit Letter <u>P</u> : <u>1177</u> Feet From The <u>South</u> Line and <u>1230</u> Feet From The <u>East</u> Line Section <u>21</u> Township <u>17S</u> Range <u>29E</u> NMPM <u>Eddy, N.M.</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3568 GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 100' cement plug 2158-2038' in and out 7" csg and circ hole with mud. TAG
2. Perf csg @ 640', squeeze perms w/50sx cmt plug in and out. and tag cmt.
3. Perf csg @ 260', squeeze perms w/50sx cmt plug in and out. TAG  
305'
4. Set 60' surface plug.
5. Install dry hole marker and cut off anchors and level location and fill in pit.



+ Notifie N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Crissa D. Carter TITLE Production Analyst DATE 8/23/00

TYPE OR PRINT NAME

Crissa D. Carter

TELEPHONE NO. (505)748-1288

(This space for State Use)

APPROVED BY Steve Stufflefield TITLE Field Rep II DATE 8/31/2000

CONDITIONS OF APPROVAL, IF ANY: