	ULITED STATES. O. C. SCHMET IN TRIDE CATE OF THE INTERIOR verse side)  GEOLOGICAL SURVEY	
	SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  Use "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	OIL X GAS OTHER  NAME OF OPERATOR	7. UNIT AGREEMENT NAME  8. FARM OR LEASE NAME
	SUN OIL COMPANY V  ADDRESS OF OPERATOR  P. O. Box 1861, Midland, Texas 79701	9. WELL NO.  7 10. FIELD AND POOL, OR WILDCAT
4.	P. O. Box 1861, Midland, Texas 79701  LOCATION OF WELL (Report location clearly and in accordance with any State requirements.)  See also space 17 below.)  At surface  330' FSL, 330' FEL Unit "P"	Grayburg Jackson Queen S  11. SEC., T., R., M., OR BLE. AND SURVEY OR AREA
14.	PERMIT NO.   15. ELEVATIONS (Show whether DF, RT, GR, etc.)   3586 DF	Sec. 22, T-17-S, R-29-E  12. COUNTY OR PARISH 13. STATE  Eddy New Mexico
16.	Check Appropriate Box to melecule victoria, replaying	·
17.	TEST WATER SHUT-OFF  FRACTURE TREAT  SHOOT OR ACIDIZE  REPAIR WELL  TEST WATER SHUT-OFF  ABANDON*  CHANGE PLANS  WATER SHUT-OFF  FRACTURE TREATMENT  SHOOTING OR ACIDIZING  (Other)  (Other)	TEPORT OF:  REPAIRING WELL  ALTERING CASING  ABANDONMENT*  ts of multiple completion on Well pletion Report and Log form.)  s, including estimated date of starting any local depths for all markers and zones perti-
1)	Rig up Pulling Unit 3/14/72	
2) 3)	Tag TD and POOH  Perforate 3210'-39' w/l JSPF. Total 30 holes (.50')	
4)	Run 2-7/8" OD, frac tubing and RTTS pkr.	
5)	Set pkr @ 3190', pressure up annulus to 500#.	
6)	Frac w/35,000 gallons gelled wtr. and 45,000 $\#$ 20/40 sand.	
7)	Pull frac tubing.	
8)	Run 2-3/8" OD tubing and place on pump.	RECEIVED
		MAR 1 1 1972  S. GEOLOGICAL SUNVER  ARTESIA, NEW MEXICE
18.	signed has May Charles Gray TITLE Proration Clerk	DATE3-13-72
<del></del>	(This space for Federal or State office use)  APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	DATE

\*See Instructions on Reverse Side