				C. C. COPY		Form approved.	y a.
Form 9-331 (May 1963)		U' TED STA					. /
(muy 1903)	DFPART	MEINT OF TH	IF INTEDI	C. C. COPY SUBMIT IN TRI (Other instructio.	on re-	Budget Bureau 1	No. 42-R1
		GEOLOGICAL		UR verse side)	5	. LEASE DESIGNATION AND	
						IC 028775 (a	<u>a)</u>
SU	NDRY NO	TICES AND R	EPORTS C	ON WELLS		. IF INDIAN, ALLOTTEE OR	TRIBE NA
(Do not use t)	us form for prop Use "APPLIC	osals to drill or to d CATION FOR PERMI	eepen or plug ba T—" for such pr	ack to a different reservoi oposals.)	ir.		
1.						. UNIT AGBEEMENT NAME	
WELL CAS THER - Water injection						Robinson-Jackson Unit	
2. NAME OF OPERATOR Shenandoah Oil Corporation					8	8. FARM OR LEASE NAME	
3. ADDRESS OF OPERA						Tract 1	
1500 Commerce Building - Fort Worth, Texas - 76102					9.	9. WELL NO. 7	
4. LOCATION OF WELL See also space 17 t	(Report location elow.)	clearly and in accord	lance with any S	State requirements.*		0. FIELD AND POOL, OR WI	LDCAT
At surface	,					Grayburg-Jackso	
1.980' FST.	and 660' F	EL Section 27	7 _ m1 70	D000		1. SEC., T., R., M., OR BLK. SURVEY OR AREA	
1,000 100		CLI SECTION 2.	7 = 11/5 =	- RZ9E		ec.27 - 17S - 2	0017
14. PERMIT NO.					د	ec.27 = 175 = 2	29E
AI, FRAMIT NU,		15. ELEVATIONS (S					STATE
			3,566	) Gr		Eddy	w Mex
16.	Check A	ppropriate Box Te	o Indicate Na	ature of Notice, Repo	ort, or Oth	er Data	
	NOTICE OF INTE		ł	·····,····		REPORT OF :	
TEST WATER SHUT	-077			<u>.</u>			<u></u>
FRACTURE TREAT		PULL OR ALTER CASI: MULTIPLE COMPLETE		WATER SHUT-OFF		BEPAIRING WELL	
SHOOT OR ACIDIZE		ABANDON*		FRACTURE TREATME		ALTERING CASING	°
BEPAIR WELL	x	CHANGE PLANS		SHOOTING OR ACIDI2		ABANDONMENT*	
(Other)	Casin	J Leak	Y		t results of	multiple completion on V	Vall
T. D. 2,97 1. Shut in 2. Pull in	or completed of If well is direct D.B.T.I n to let pr njection to	EBATIONS (Clearly sta ionally drilled, give s D. 2,955' ressure bleed lhing, packer	te all pertinent ubsurface location off cs and dow	details, and give pertine ons and measured and tru m-hole flow req	nt dates, inc ue vertical de	n Report and Log form.) luding estimated date of epths for all markers and	
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru m-hole flow req ocker and plug	nt dates, incluse vertical de	n Report and Log form.) luding estimated date of epths for all markers and	
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru m-hole flow req	nt dates, incluse vertical de	n Report and Log form.) luding estimated date of epths for all markers and	
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru m-hole flow req ocker and plug	nt dates, incluse vertical de	n Report and Log form.) luding estimated date of epths for all markers and	
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru m-hole flow req ocker and plug	nt dates, incluse vertical de	n Report and Log form.) luding estimated date of epths for all markers and	
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru m-hole flow req ocker and plug	nt dates, inci ue vertical de nulators	in Report and Log form.) luding estimated date of epths for all markers and	starting a
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru on-hole flow req ocker and plug ad San Andres Zo	nt dates, inci ue vertical de nulators	in Report and Log form.) luding estimated date of epths for all markers and	starting a
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru m-hole flow req ocker and plug	nt dates, inci ue vertical de nulators	in Report and Log form.) luding estimated date of epths for all markers and	starting a
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	REC	details, and give pertine ons and measured and tru on-hole flow req ocker and plug ad San Andres Zo	nt dates, inci ue vertical de fulators	RECEIV	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	l off s and dow leak w/pa	details, and give pertine ons and measured and tru m-hole flow req ocker and plug ad San Andres Zo	nt dates, inci ue vertical de fulators	RECEIV	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	REC	details, and give pertine ons and measured and tru on-hole flow req ocker and plug ad San Andres Zo	nt dates, inci ue vertical de fulators	RECEIV	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	REC APR C. C	details, and give pertine ons and measured and tru m-hole flow req icker and plug id San Andres Zo 9 1975	nt dates, inci ue vertical de fulators	RECEIV	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or conversion to f well is direction b. D.B.T.I n to let pr njection to for channel and repain	EBATIONS (Clearly stationally drilled, give s c. 2,955' ressure bleed abing, packer l and casing c as necessar	REC APR C. C	details, and give pertine ons and measured and tru m-hole flow req ocker and plug ad San Andres Zo	nt dates, inci ue vertical de fulators	RECEIV	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement	or completed of f well is direction to let pro- n to let pro- n to channel and repain l back on	ERATIONS (Clearly sta ionally drilled, give s D. 2,955' ressure bleed ubing, packer l and casing r as necessar injection in	REC APR C. C	details, and give pertine ons and measured and tru m-hole flow req icker and plug id San Andres Zo 9 1975	nt dates, inci ue vertical de fulators	in Report and Log form.) luding estimated date of epths for all markers and	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement 5. Put we	or completed of f well is direction to let pro- n to let pro- n to channel and repain l back on	ERATIONS (Clearly sta ionally drilled, give s D. 2,955' ressure bleed ubing, packer l and casing r as necessar injection in	REC APR C. C. C. APR	EIVED 9 1975 Completion or details, and give pertine; ons and measured and tru m-hole flow req icker and plug d San Andres Zo 9 1975 C. C. PEFICE	U.	RECEIVA APR - 7 1975 S. GEOLOGICAL SURV RTESIA, NEW MEXICO	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement 5. Put we 8. I hereby certify the SIGNED	or completed of the foregoing is the foregoing	ERATIONS (Clearly sta ionally drilled, give s D. 2,955' ressure bleed abing, packer and casing r as necessar injection in s true and correct	REC APR C. C. C. APR	details, and give pertine ons and measured and tru m-hole flow req icker and plug id San Andres Zo 9 1975	U.	RECEIV	starting a l zones pe
T. D. 2,97 1. Shut in 2. Pull in 3. Check 4. Cement 5. Put we 8. I hereby certify tha	or completed of the foregoing is the foregoing	ERATIONS (Clearly sta ionally drilled, give s D. 2,955' ressure bleed abing, packer and casing r as necessar injection in s true and correct	REC APR C. C. C. APR	EIVED 9 1975 Completion or details, and give pertine; ons and measured and tru m-hole flow req icker and plug d San Andres Zo 9 1975 C. C. PEFICE	U.	RECEIVA APR - 7 1975 S. GEOLOGICAL SURV RTESIA, NEW MEXICO	starting a l zones pe
a. D. 2,975   1. Shut in 2.   2. Pull in 3. Check   4. Cement 5. Put we   5. Put we Signed C.   8. I hereby certify that Signed C. W.   (This space for Fed APPROVED BY C. W.	or COMPLETED OF If well is direction to let pro- n to let pro- n to let pro- n to channel and repain l back on t the foregoing is <u>Downey, to</u> eral or State off	ERATIONS (Clearly stationally drilled, give s D. 2,955' ressure bleed ubing, packer l and casing r as necessar injection in s true and correct Dr. ce use)	REC APR C. C. C. APR	EIVED 9 1975 Completion or details, and give pertine; ons and measured and tru m-hole flow req icker and plug d San Andres Zo 9 1975 C. C. PEFICE	U.	RECEIVI APR - 7 1975 RTESIA, NEW MEXICO DATE March 2,	starting a l zones pe
a. D. 2,97   I. Shut in   2. Pull in   3. Check   4. Cement   5. Put weight   8. I hereby certify that   SIGNED   C. W.   (This space for Fed)	or COMPLETED OF If well is direction to let pro- n to let pro- n to let pro- n to channel and repain l back on t the foregoing is <u>Downey, to</u> eral or State off	ERATIONS (Clearly stationally drilled, give s D. 2,955' ressure bleed ubing, packer l and casing r as necessar injection in s true and correct Dr. ce use)	REC APR TITLE Ope	EIVED 9 1975 Completion or details, and give pertine; ons and measured and tru m-hole flow req icker and plug d San Andres Zo 9 1975 C. C. PEFICE	U.	RECEIVA APR - 7 1975 S. GEOLOGICAL SURV RTESIA, NEW MEXICO	starting a l zones pe
a. D. 2,975   1. Shut in 2.   2. Pull in 3. Check   4. Cement 5. Put we   5. Put we Signed C.   8. I hereby certify that Signed C. W.   (This space for Fed APPROVED BY C. W.	or COMPLETED OF If well is direction to let pro- n to let pro- n to let pro- n to channel and repain l back on t the foregoing is <u>Downey, to</u> eral or State off	ERATIONS (Clearly stationally drilled, give s D. 2,955' ressure bleed ubing, packer l and casing r as necessar injection in s true and correct Dr. ce use)	REC APR TITLE Ope	EIVED 9 1975 Completion or details, and give pertine; ons and measured and tru m-hole flow req icker and plug d San Andres Zo 9 1975 C. C. PEFICE	U.	RECEIVI APR - 7 1975 RTESIA, NEW MEXICO DATE March 2,	starting a l zones pe
a. D. 2,975   1. Shut in 2.   2. Pull in 3. Check   4. Cement 5. Put we   5. Put we Signed C.   8. I hereby certify that Signed C. W.   (This space for Fed APPROVED BY C. W.	or COMPLETED OF If well is direction to let pro- n to let pro- n to let pro- n to channel and repain l back on t the foregoing is <u>Downey, to</u> eral or State off	ERATIONS (Clearly stationally drilled, give s D. 2,955' ressure bleed ubing, packer l and casing r as necessar injection in s true and correct Tr. ce use)	REC APR TITLE	details, and give pertine ons and measured and true m-hole flow required toker and plug and San Andres Zo $E I \vee E D$ 9 1975 C.C. Parice rations Superin	U.	RECEIVI APR - 7 1975 RTESIA, NEW MEXICO DATE March 2,	starting a l zones pe
a. D. 2,975   1. Shut in 2.   2. Pull in 3. Check   4. Cement 5. Put we   5. Put we Signed C.   8. I hereby certify that Signed C. W.   (This space for Fed APPROVED BY C. W.	or COMPLETED OF If well is direction to let pro- n to let pro- n to let pro- n to channel and repain l back on t the foregoing is <u>Downey, to</u> eral or State off	ERATIONS (Clearly stationally drilled, give s D. 2,955' ressure bleed ubing, packer l and casing r as necessar injection in s true and correct Tr. ce use)	REC APR TITLE	EIVED 9 1975 Completion or details, and give pertine; ons and measured and tru m-hole flow req icker and plug d San Andres Zo 9 1975 C. C. PEFICE	U.	RECEIVI APR - 7 1975 RTESIA, NEW MEXICO DATE March 2,	starting a l zones pe