Submit 3 Conies To Annonright District	State of Now X45 123456	
Submit 3 Copies To Appropriate District Office	State of New Indexico	Form C-103
District 1	gy, Minerals and Matural Resources	Revised March 25, 1999 WELL API NO.
District I  1625 N. French Dr., Hobbs, NM 88240  District II  1301 W. Grand Avenue, Artesia, NM 88240  District III  1000 Rio Brazos Rd., Aztec MM 87410  District IV  1220 S. St. Francis Dr. Santa Pr. 884 87505	CONSERVATION DIVISION	30-015-03192
District III	1220 South St. Francis DVED	Indicate Type of Lease
1000 Rio Brazos Rd., Aztec MM 87410	Santa Fe, NM 87505 ARTESIA	STATE FEE
1220 5: 5: 1141013 51., 54114 1 4 7 6 7	/ \4,	₹6. State Oil & Gas Lease No. LC 062407
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO DR DIFFERENT RESERVOIR. USE "APPLICATION FOR	REPORTS ON WELLS	7. Lease Name or Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DR	ILL OR TO DEEPEN OR TURG BACKSTON	
PROPOSALS.)	PERMIT" (FORM C-101) FOR SUCH	EMPIRE ABO UNIT " C "
1. Type of Well:	LINDEDODOLIND IN IECT	
	her UNDERGROUND INJECT.	O. W. I. N.
2. Name of Operator BP AMERICA P		8. Well No. 48
3. Address of Operator P.O. BOX 1089 EUNICE, NM 88231		9. Pool name or Wildcat EMPIRE ABO UNIT
4. Well Location		
Unit Letter   1 : 1980   feet from the   S   line and   990   feet from the   E   line		
Section 30 Township 17S Range 29E NMPM EDDY County		
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTIO		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AN	ND ABANDON REMEDIAL WO	RK ALTERING CASING
TEMPORARILY ABANDON CHANGE	PLANS COMMENCE DE	
PULL OR ALTER CASING MULTIPL	E CASING TEST A	ABANDONMENT
COMPLE		
	CEMENT JOB	
OTHER: REPAIR BRADENHEAD LEAD  12. Describe proposed or completed opera	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a	nd give pertinent dates, including estimated date
OTHER: REPAIR BRADENHEAD LEAD  12. Describe proposed or completed opera of starting any proposed work). SEE RUI	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a	
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a  LE 1103. For Multiple Completions: Atta	nd give pertinent dates, including estimated date
OTHER: REPAIR BRADENHEAD LEAD  12. Describe proposed or completed opera of starting any proposed work). SEE RUI	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a  LE 1103. For Multiple Completions: Atta	nd give pertinent dates, including estimated date
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a  LE 1103. For Multiple Completions: Atta  56 - 6266 'CIBP: 5995'	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I. WELL FAILED BRADENHEAD TES	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  256 - 6266 'CIBP: 5995'  Notify Or perforation	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I. WELL FAILED BRADENHEAD TESPRESS. AND CHARTED CSG. 50	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  256 - 6266 'CIBP: 5995'  ST.  15# - 495# IN 30 MIN.	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please of proposed completion of cementing
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I. WELL FAILED BRADENHEAD TES	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  256 - 6266 'CIBP: 5995'  ST.  15# - 495# IN 30 MIN.	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When any depth is established please
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I. WELL FAILED BRADENHEAD TESPRESS. AND CHARTED CSG. 50	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  256 - 6266 'CIBP: 5995'  ST.  15# - 495# IN 30 MIN.	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please of proposed completion of cementing
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TEST PRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON WINTENT: 120 DAYS  MIRUPU. NDWH. NUBOP.	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  56 - 6266 ' CIBP: 5995'  ST.  95# - 495# IN 30 MIN.  ACUUM.  CEMENT JOB  OTHER:  Notify Or  perforating contact Contac	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please of proposed completion of cementing
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TEST PRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON WENT	CEMENT JOB  CEMENT JOB  CHART JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  SECTION  CEMENT JOB  OTHER:  Notify Or perforating contact	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please oCD for confirmation of cementing e. 505-748-1283
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TESPRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VINTENT: 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estab	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  56 - 6266 ' CIBP: 5995'  ST.  95# - 495# IN 30 MIN.  ACUUM.  CEMENT JOB  OTHER:  Notify Or  perforating contact Contac	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please oCD for confirmation of cementing e. 505-748-1283
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TEST PRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON WENT	CEMENT JOB  CEMENT JOB  CHART JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  SECTION  CEMENT JOB  OTHER:  Notify Or perforating contact	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please oCD for confirmation of cementing e. 505-748-1283
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TESPRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VINTENT: 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estab	CEMENT JOB  CEMENT JOB  CHART JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  SECTION  CEMENT JOB  OTHER:  Notify Or perforating contact	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please oCD for confirmation of cementing e. 505-748-1283
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TESPRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VINTENT: 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estable back side.	CEMENT JOB  CEMENT JOB  CHART	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please oct of confirmation of cementing e. 505-748-1283  d cement squeeze up bradenhead
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TESPRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VINTENT: 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estab	CEMENT JOB  CEMENT JOB  CHART	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please oct of confirmation of cementing e. 505-748-1283  d cement squeeze up bradenhead
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TESPRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VINTENT: 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estable back side.	CEMENT JOB  CEMENT JOB  CHART	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please oct of confirmation of cementing e. 505-748-1283  d cement squeeze up bradenhead
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TEST PRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VIOLENTE 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estable back side.	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  56 - 6266 ' CIBP: 5995'  OT.  OST.	nd give pertinent dates, including estimated date ch wellbore diagram of proposed completion  CD 24 hrs prior to work. When ag depth is established please occ process of confirmation of cementing e. 505-748-1283  d cement squeeze up bradenhead
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TEST PRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VIOLENTE 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estable back side.	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  56 - 6266 ' CIBP: 5995'  OT.  OST.	and give pertinent dates, including estimated date the wellbore diagram of proposed completion  CD 24 hrs prior to work. When the depth is established please of the confirmation of cementing the confirmation of cementing the confirmation of cementary the confirmation of cemen
OTHER: REPAIR BRADENHEAD LEAI  12. Describe proposed or completed opera of starting any proposed work). SEE RUI or recompilation.  TD: 6360' PBTD: 6343' PERFS: 62  WELL S.I.  WELL FAILED BRADENHEAD TEST PRESS. AND CHARTED CSG. 50  PRESS. BH TO 110#, WENT ON VIOLENT: 120 DAYS  MIRUPU. NDWH. NUBOP.  Load & press test back side of csg to OK - will POH w/tbg, perf csg ,estable back side.  I hereby certify that the information above is to SIGNATURE.  Type or print name	CEMENT JOB  CEMENT JOB  OTHER:  tions. (Clearly state all pertinent details, a LE 1103. For Multiple Completions: Atta  56 - 6266 ' CIBP: 5995'  OT.  OST.	and give pertinent dates, including estimated date the wellbore diagram of proposed completion  CD 24 hrs prior to work. When the depth is established please of the confirmation of cementing the confirmation of cementing the confirmation of cementary the confirmation of cemen