

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. <u>30-05-03116</u>
Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
State Oil & Gas Lease No. E-537
Lease Name or Unit Agreement Name C-State
Well No. 2
Pool name or Wildcat Grbg Jackson Sr Q Grbg SA

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
Name of Operator Webb Oil Company	Well No. 2
Address of Operator 2409 Cerro Road, Artesia, NM, 88210-9757	Pool name or Wildcat Grbg Jackson Sr Q Grbg SA
Well Location Unit Letter <u>J</u> : <u>1650</u> Feet From The <u>South</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>17S</u> Range <u>29S</u> NMPM <u>Eddy</u> County	
Elevation (Show whether DF, RKB, RT, GR, etc.) 3424GR	

11

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: ☐


### SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ANBANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Notify Ocd 24 Hrs. before starting

1. RIH spot 100' plug in 4 1/2 @ 2800 (perf. 2876 to 2890) TAG
2. Spot 100' plug @ 725 (bottom salt 675) \* Perforate 4 1/4" csg @ 725, squeeze 100' cement Plug. Inside + Outside Csg. TAG
3. ~~Spot 100' plug @ 440 sqz.~~ 100' plug (top salt 3360) woc tag \* Perforate 100' cement Plug. Inside + Outside Csg. TAG
4. ~~spot cmt. 30' to surface~~ \* Perforate 4 1/4" csg. Circulate cement casing. TAG
5. cut off well head install dry hole marker to surface.



\* Brine gel between all cement Plugs.

Notifie N.M.O.C.D. to witness Plugging Operations.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Wayne Brooks RDB TITLE agent DATE 05-02-01

TYPE OR PRINT NAME Wayne Brooks TELEPHONE NO. 915-5807161

(This space for State Use)

APPROVED BY mae Steelfield TITLE Envir. Eng. Spec. I DATE 5/8/2001

CONDITIONS OF APPROVAL, IF ANY: