Submit 3 Copies To Appropriate District District 1 1625 N. French Dr., Hobbs, NM 88240 505 MJ 50	
Submit 3 Copies To Appropriate District T State of New Mexico	Form C-
District I	Revised March 25, 1 WELL API NO.
	30-015-04047
District II F RECEIVED 811 South First, Artesia, Nue 88210CD - ARTESIA, CONSERVATION DIVISION	5. Indicate Type of Lease
100 Pio Prome Pd. Area Md 87410	STATE S FEE
District IV Santa Fe, NM 8/304	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, 14187504	B-3635-46
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement N
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	BURNHAM GB SA UNIT
PROPOSALS.) 1. Type of Well:	TR. 2
Oil Well 🖾 Gas Well 🗌 Other	1 20
2. Name of Operator	8. Well No.
CBS OPERATING CORP.	3
3. Address of Operator P O BOX 2236, MIDLAND TX 79702	9. Pool name or Wildcat
4. Well Location	SOUARE LAKE GB SA
4. Well Location	
Unit Letter I : 1980 feet from the South line and	60 feet from the east
Section 2 Township 17S Range 30E	<u>NMPM Eddy County NM</u>
10. Elevation (Show whether DR, RKB, RT, GR 3773' GL	etc.)
11. Check Appropriate Box to Indicate Nature of Notic	e Report or Other Data
	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL W	DSEQUENT REPORT OF:
	DRK ALTERING CASIN
	DRILLING OPNS. PLUG AND ABANDONMENT
	ORILLING OPNS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB	DRILLING OPNS. PLUG AND ABANDONMENT Idle Well
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: Res	DRILLING OPNS PLUG AND ABANDONMENT AND Idle Well store to Production
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details	DRILLING OPNS. PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At	DRILLING OPNS. PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: 12. Describe proposed or completed operations. (Clearly state all pertinent details	DRILLING OPNS. PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH	DRILLING OPNS. PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, dro
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressure	ORILLING OPNS. PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, dro ce up on tubing, would r
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with	DRILLING OPNS. PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, dro ce up on tubing, would r in tubing. Laid down 17 k
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17	DRILLING OPNS PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, dro ce up on tubing, would r tubing. Laid down 17 h joints and test tubing h
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with	DRILLING OPNS PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, dro ce up on tubing, would r tubing. Laid down 17 h joints and test tubing h
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. OTHER: Res 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. OTHER: Res 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD	DRILLING OPNS PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, drops and pump, drops ce up on tubing, would rest tubing. Laid down 17 here joints and test tubing here
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production.	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production.	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production.	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production.	DRILLING OPNS PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, drops and pump, drops ce up on tubing, would rest tubing. Laid down 17 here points and test tubing here pump and turn well to
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production.	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production.	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. OTHER: Res 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production. I hereby certify that the information above is true and complete to the best of my know SIGNATURE	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production.	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. OTHER: Res 12-26-02 MI & RU JOE'S Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production. I hereby certify that the information above is true and complete to the best of my know SIGNATURE M. A. SIRGO, III Type or print name	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. OTHER: Res 12-26-02 MI & RU JOE'S Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900 #, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production. I hereby certify that the information above is true and complete to the best of my know SIGNATURE M. A. SIRGO, III Type or print name M. A. SIRGO, III	DRILLING OPNS PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, drops and pump, drops and pump, would rest tubing. Laid down 17 here up on tubing. Laid down 17 here up and test tubing here to pump and turn well to veldge and belief. DATE1-21-2 Telephone N&15/685
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 MI & RU JOE'S Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 Took off BOP. RIH with rods and production. I hereby certify that the information above is true and complete to the best of my know SIGNATURE M. A. SIRGO, III Type or print name M. A. SIRGO, III	DRILLING OPNS PLUG AND ABANDONMENT AND
TEMPORARILY ABANDON CHANGE PLANS COMMENCE I PULL OR ALTER CASING MULTIPLE COMPLETION CASING TEST CEMENT JOB OTHER: OTHER: OTHER: Res 12. Describe proposed or completed operations. (Clearly state all pertinent details of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompilation. 12-26-02 - MI & RU Joe's Well Service. POH standing valve. Tried to pressur hold. Rigged up BOP and POH with joints of tubing. Picked up 17 in hole to 900#, tested okay. SD 12-27-02 - Took off BOP. RIH with rods and production. I hereby certify that the information above is true and complete to the best of my know SIGNATURE M. A. SIRGO, III Type or print name M. A. SIRGO, III	DRILLING OPNS PLUG AND ABANDONMENT AND Idle Well store to Production and give pertinent dates, including estimate tach wellbore diagram of proposed complet with rods and pump, drops and pump, drops and pump, would rest tubing. Laid down 17 here up on tubing. Laid down 17 here up and test tubing here to pump and turn well to veldge and belief. DATE1-21-2 Telephone N&15/685

•