NN OIL CONS. COMMISSION

Drawer DD UN. . LD STATES Artesia. THE MERCITOR INTERIOR OF THE INTERIOR Verse side) Form approved, Budget Bureau No. 42-R1424. (May 1963) 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY LC-029020L SUNDRY NOTICES AND REPORTS ON WELLS IF INDIAN, ALLOTTEE OR TRIBE NAME (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.) 7. UNIT AGREEMENT NAME WELL GAS MELL XX OTHER O. C. D. NAME OF OPERATOR 8. FARM OR LEASE NAME ARTESIA, OFFICE Southland Royalty Company <u>Dexter Federal</u> 1100 Wall Towers West, Midland, Texas LOCATION OF WELL (Report location clearly and in accordance See also space 17 below.) 79701 <u>Texas</u> with any State requirements. 10. FIELD AND POOL, OR WILDCAT <u> Grayburg Jackson (SR-O-GB-SA)</u> 1650' FSL & 1650' FEL, Sec. 15, T-17-S, R-30-E 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 15, T-17-S, R-30-E 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3697' DF N.M. 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

(Other) . (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other) Revised procedure to Convert to Injection 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

- 1. MIRU CU, install BOP, RIH w/3 7/8" bit & csg scraper on 2 3/8" WS to PBTD (+ 3511) circulate hole clean. POOH.
- RIH w/COBP on wireline and set @ 1665', test csg to 2000 psi.

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

- If no csg leak exists, perf w/4 way SQZ gun @ 1650'
- 4. RIH w/cement retainer on WL and set @ 1630'.

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

- RIH w/WS and sting into retainer. Attempt to break circulation with brine water. Circulate cement (Use lite cmt w/18# salt per sk followed by Cl "C" neat w/2% CaCl2). We must displace cement up to a minimum of 1125' (base of salt). Sting out of retainer and reverse out.
- RIH w/bit & DC on work string and drill out to PBTD, POOH. Run temp survey.
- Perf Premier 2860'-78' & Metex 2747-52', 1 JSPF, 25 holes, w/ 3 5/8" csg guns per Welex Radioactivity Log dated 4/8/60.
- RIH w/RBP & pkr on 2 3/8 WS. Set RBP @ + 2950', pkr @ + 2650'. Pressure up backside to 500 psi.
- B. J. Hughes acdz perfs @ 2747'-2878' w/2500 gal 15% NEHCl dropping 6 RCNB every 10 bbl of acid pumped. Flush w/18 bbl lease water. Swab back load. Retrieve RBP and POOH.
- 10. RIH w/plastic coated Baker Mod A-2 Loc-Set pkr on 2 3/8" plastic coated tbg to + 2700'. Load backside w/30 bbls treated fresh water. Set pkr.
- RD CU. Place well on injection.

SIGNED APPROVED	TITLE _	District Operations Engineer 5/7/82
(This space for Federal or State office use) (Ong. Sgd.) PETER W. CHESTER APPROVED BY CONDITIONS OF APPROMAY IF GRASS	TITLE _	DEGENOVE DATE
FOR JAMES A. GILLHAM DISTRICT SUPERVISOR *S	e Instruct	Link I was a