Submit 3 Copies to Appropriate District Office

APPROVED BY-

CONDITIONS OF APPROVAL, IF ANY

State of New Mexico Energy, Minerals and Natural Resources Department

151 Form C-103

DISTRICT I P.O. Box 1980, Hobbs NM 88240

OIL CONSERVATION DIVISION

Ī	Revised 1-1-89
	WELL API NO.
	30-015-04163 5. Indicate Type of Lease
	STATE STATE
	6. State Oil & Gas Lease No. B-3138
	7. Lease Name or Unit Agreement Name
1	Juniper State
1	8. Well No. 3
/	9. Pool name or Wildcat
	Grbg Jackson SR Q Grbg SA
99	0 Feet From The West Line
1	MPM Eddy County
Re	port, or Other Data
BSEQUENT REPORT OF:	
	ALTERING CASING
NG	OPNS. PLUG AND ABANDONMENT
CEI	MENT JOB
incl	uding estimated date of starting any proposed
1u!	st tag No Lower than 1952'
- 100' plug 1765'-1865'- 1799 1070-Squeeze Cont (00'); ns: de 1	
. (4.9	
csq. Strings from 475-575 - Tas	
csf. Strings from 475-575 - 125	
ns 85/67" + 547, Cric. Cm7	
Le all es; strings from 0-60'	

2040 South Pacheco Santa Fe, New Mexico 87505 811 South First, Artesia, NM 88210 DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLA DIFFERENT RESERVOIR. USE "APPLICATION FOR PER 611 8 9 70 (FORM C-101) FOR SUCH PROPOSALS) 1. Type Of Well: OIL GAS X OTHER WELI WEL 2. Name of Operator Mack Energy Corporation 3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960 4. Well Location South Feet From The Unit Letter 16 17S 30E Township Range 10. Elevation (Show whether DF, RKB, RT, GR, etc.) Check Appropriate Box to Indicate Nature of Notice, NOTICE OF INTENTION TO: SU PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLII PULL OR ALTER CASING CASING TEST AND OTHER: OTHER 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, work) SEE RULE 1103. Mack Energy Corporation proposes to plug as follows 5 TSet ID' cement plug 50' above and below easing shec from 2130'-250'. WOC and tag. 🖊 2. Set 100' cement plug 50' above and below base of salt from 2000-1100'. WOC and tag. 1070'- 970' F pay cog @ 3. Set 10 sx cement plug at surface. Outside esq 4. Clean up move off and install dry hole marker. Outside both Salt gel mud consisting of 10# Perfall ess. still Brine W/25# of gel per bbl must be placed between each plug Notify OCD 24 hrs. prior to any work done I hereby certify that the information above is true and comprese to the best of my knowledge and belief. 2/7/02 **Production Analyst** DATE SIGNATURE TELEPHONE NO. 748-1288 Crissa D. Carter TYPE OR PRINT NAME (This space for State Use)