Submit 3 Copies to Appropriate District Office

1. Type Of Well:

4. Well Location

 \boxtimes

Mack Energy Corporation 3. Address of Operator

Section

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER: TA well

3. Spot 10 sy su

OIL

WEL 2. Name of Operator

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 1-1-89

DISTRICT I P.O. Box 1980, Hobbs NM 88240

DISTRICT II 811 South First, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410

GAS

P.O. Box 960, Artesia, NM 88211-0960

OIL CONSERVATION DI

SUNDRY NOTICES AND REPORTS ON WELLS

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG

OIL CONSERVATION DIVISION 2040 South Pacheco					API NO.			
88210	Santa Fe, New Mexico 87505				5. Indicate Type of Lease STATE FEE			
M 87410					6. State Oil & Gas Lease No.			
DRY NOTICES AND REPORTS ON WELLS M FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A RENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).					7. Lease Name or Unit Agreement Name			
OTHER				Rand	Randel State			
				1	eli No.			
4 00011 0060					9. Pool name or Wildcat			
1 88211-0960					Grbg Jackson SR Q Grbg SA			
990	Feet From The	North	Line and	2310	_ Feet From The	West	Line	
6	Township 17	7S Ra	nge 30E	NMPM	Eddy	7	County	
		•	DF, RKB, RT, GR, et 3681'	c.)		a.		
Check Ap	propriate Box to	Indicate N	Nature of Notic	e, Report,	or Other Data			
OF INTE	NTION TO:	SUBSEQ	JBSEQUENT REPORT OF:					
	PLUG AND ABAN	DON 🛛	REMEDIAL WOR	ĸĸ	ALTER	ING CASING		
	CHANGE PLANS		COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT					
			CASING TEST AND CEMENT JOB					
			OTHER					

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give work) SEE RULE 1103.

Mack Energy Corporation proposes to PA the Randel State #1 as follows.

NOTICE OF INTENTION TO:

02/07/2002 Spoted 100sx cement plug at 1850'. WOC and tagged at 1570'. Spotted 50sx plug at 1570' WOC and tagged at 1201'.

1. Perforate casing at base of salt. Squeeze cement inside and outside of 7" casing. WOC and tag.

2. Perforate casing at top of salt. Squeeze cement inside and outside of 7" casing. WOC and tag.

3. Spot 10 sx surface slip.

Salt gel mud consisting of 10#
Brine W/25h at get per bbl
must be placed between each plug

Perf 898 € 7" @ 300'- Squeeze 100' of ent inside ? centrale

Both Strips of Pipe 200-300'

Perf 8578: ?" @ 60'- Squeeze 60' of ent. inside ? outside

Of Both Strips. 0'-60'

I hereby certify that the information above is true and comp	and to the best of my knowledge and belief.	Production Analyst	DATE
TYPE OR PRINT NAME	Crissa D. Carter		TELEPHONE NO. 748-1288

July Hap 19 (This space for State Use)

CONDITIONS OF APPROVAL, IF ANY

APPROVED BY-

