00-00-04179

2-20-73

BNC accusting

Samma Ray Heutron

Est Geal. Tops par 1BO Rustler Grayburg 2580 San Andre > 2820 275 525 Salado 995 B Satt 1225 yates 150c 7 Rivers 19cc Bours Queen 2080

	ur.			· · · · · ·	
	State of ?	Mary NA	'ovice	CUSA	
Submit 3 Copies to Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources Department			4)	Form C-103 Revised 1-1-89
<u>DISTRICT I</u> P.O. Box 1980, Hobbs NM 88240	OIL CONSERVATION DIVISION 2040 South Pacheco			WELL API NO.	
DISTRICT II 811 South First, Artesia, NM 88210	Santa Fe, New	v Mex	tico 87505	30-015-04179 5. Indicate Type of Lea	se 🔽 🗔
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410			5161718192027 ₂₂₂₃	6. State Oil & Gas Leas	STATE FEE
			6	B-3138	
(DO NOT USE THIS FORM FOR PR DIFFERENT RES (FORM	TICES AND REPORTS COPOSALS TO DRILL OR TO DI SERVOIR. USE "APPLICATION 1C-101) FOR SUCH PROPOSAL	ON (A) EEPE 2 0 I FOI (2)	ELLS ()	7. Lease Name or Unit	Agreement Name
1. Type Of Well: OIL GAS WELL WELL	OTHER	15	So Sulphi	Juniper State	
2. Name of Operator Mack Energy Corporation			38251-15	8. Well No.	
3. Address of Operator				9. Pool name or Wildca	t
P.O. Box 960, Artesia, NM 88211-0960				Grbg Jackson SR Q Grbg SA	
4. Well Location					
Unit LetterM :330	Feet From The S	outh	Line and 99	Po Feet From The	West Lir
Section 16	Township 17S	Ra	ange 30E	имрм Ес	ldy County
		whether	DF, RKB, RT, GR, etc.) 665' GR		County County
11. Check	Appropriate Box to Ind	icate l	Nature of Notice Re	eport or Other Da	3
NOTICE OF INT				SEQUENT REPO	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	\boxtimes	REMEDIAL WORK	ALTE	ERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING	OPNS. PLU	G AND ABANDONMENT (
PULL OR ALTER CASING			CASING TEST AND CE	MENT JOB	
OTHER:			OTHER		[
12. Describe Proposed or Completed (work) SEE RULE 1103.	Operations (Clearly state all pertin	nent detai	ils, and give pertinent dates, inc	cluding estimated date of star	ting any proposed
Mack Energy Corporation proposes t	o plug and abandon well as	s follov	vs:		
 Notify OCD 24 hours prior to star Set 100' cement plug 50' above and Set 100' cement plug 50' above and Set 10 ox surface plug. 	d below bottom of salt from		.975'. — Tai	l Csq. @ 575	place 100 d itside of C59.
5. Install dry hole marker.			\ . '	, , , <u>, , , , , , , , , , , , , , , , </u>	4.1 A 059
5. Histair dry Hole Harker.			Cm ⁻	t inside : au	its.de of
Salt gel mud consisting of l	10#	<u></u>	47	5'-575'- 7	9 5 2
Brine W/25# of gel per bl					
must be placed between each				ess. @60'-	cuc emt
Notify OCD 24 hrs. prior to any s	vork done		0'-	-60'	

Production Analyst

10/21/02

TYPE OR PRINT NAME

SIGNATURE .

Crissa D. Carter

TELEPHONE NO.

DATE -

(This space for State Use)

APPROVED BY-

OCT 2 5 2002

CONDITIONS OF APPROVAL, IF ANY: