

General American Oil Co. of Texas

Subsequent Report of Sandell, Page #2  
Maddren-Beeson 6-B.

December 15, 1954

RESULTS OF TREATMENT: (Cont'd).

11-15-54 Swabbed 20 bbls.  
11-16-54 Swabbed 10 bbls. Cleaned out.  
11-17-54 Re-ran 2" NUE tubing & pump installation.  
11-18-54 Pumped 30 bbls.  
11-19-54 Pumped 29 bbls.  
11-20 thru  
11-30 Pumped 300 bbls. (NET 4 BO).

SUBSEQUENT TESTS:

12- 9-54 Pumped 14 BO.  
12-10-54 Pumped 18 BO.  
12-11-54 Pumped 16 BO.  
12-12-54 Pumped 18 BO. (NET 200 BO).

It can follow to have happened  
and no less certain

000000 7-10-68 1 00000

12111 May 1966

.06 01 bequim 48-41-81  
 .06 01 bequim 48-01-81  
 .06 01 bequim 48-11-81  
 .06 01 bequim 48-01-81  
 .(06 005 TAV)