

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

PERMIT IN TRIP  
(Other instruction  
verse side)

TE  
re

Form approved  
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC 029435 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

J. L. Keel "B"

9. WELL NO.

26

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson OGSA

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

6-17S-31E

12. COUNTY OR PARISH

Eddy

N.M.

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

RECEIVED

2. NAME OF OPERATOR

Atlantic Richfield Company

MAY 10 1976

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

O. C. C.

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.)  
At surface

ARTESIA, OFFICE

660' FSL & 516.8' FWL (Unit Letter M)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3776' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OF ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON\* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT\* ☐

(Other) Abandon present perfs, hold TA X

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.\*

This well was worked over in the Grayburg Jackson (OGSA) zone and the workover was unsuccessful. This well tested 1 BO & 280 BW in 24 hrs on 10/22/75 after WO & on 2/9/76 the well was producing 100% water & was shut in. Propose to abandon present perfs to shut off water and hold well temporarily abandoned in order to evaluate Fren Seven Rivers interval in the following manner:

1. Rig up, kill well, install BOP & POH w/completion assy.
2. RIH w/7" cmt retr on 2-3/3" tbg & set retr @ 2788'.
3. Squeeze cmt perfs 2888-3226' w/200 sx Cl C cmt cont'g 4% gel & 6# salt/sk. POH w/tbg & stinger.
4. Fill hole w/fresh corrosion inhibited water, install 2" gate valve on wellhead & temporarily abandon.

RECEIVED

MAY - 7 1976

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 5/6/76


(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side



ATLANTIC RICHFIELD COMPANY  
Blow Out Preventer Program

Lease Name J. L. Keel "B"

Well No. 26

Location 660' FSL & 516.8' FWL  
Sec 6-17S-31E, Eddy County

**RECEIVED**

MAY - 7 1976

U. S. GEOLOGICAL SURVEY  
ARTESIA, NEW MEXICO

BOP to be tested before installed on well and will be maintained in good working condition during drilling. All wellhead fittings to be of sufficient pressure to operate in a safe manner.