State of New Mexico Energy. ... aerals and Natural Resources Department

Form C-103 **Revised 1-1-89**

STATE

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

DISTRICT II P.O. Drawer DD, Artesia, NM 88210

OIL CONSERVATION DIVISION

2040 Pacheco St. Santa Fe, NM 87505 WELL API NO. 30-0

15-2	1221	3	

Indicate Type of Lease

FEE

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410				«State Oil & Gas Lea B-1483	se No.	
SUNDRY NOTICES AND R (DO NOT USE THIS FORM FOR PROPOSALS TO D DIFFERENT RESERVOIR. USE "AF (FORM C-101) FOR SUC	RILL OR TO DEEP PPLICATION FOR	EN OR PLUG BA	CK TO A	7Lease Name or Unit ETZ State Unit	_	
Type of Well: OIL GAS WELL WELL	OTHER	67.5	1	\		
aName of Operator Mack Energy Corporation		OCORECEIVE		Well No. 115		
Address of Operator P.O. Box 960 Artesia, NM 88211-0960		ARTES!		/•Pool name or Wildo Grbg Jackson		<u> </u>
•Well Location Unit Letter O : 330 Feet From The	South	Oldine and	1650	Feet From The	East	Line
Section 16 Township	178	Range	30E	NMPM	Eddy	County
oElev 3670	ration (Show whether 6GR	DF, RKB, RT, GR, (etc.)			

11 CI	neck Appro	opriate Box to Indic	ate Na	ture of Notice, Report, or	Other [Data	
NOTICE	OF INTE	NTION TO:		SUBSEQUE	NT RE	PORT OF:	
PERFORM REMEDIAL WORK		PLUG AND ABANDON	\boxtimes	REMEDIAL WORK		ALTERING CASING	
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE DRILLING OPNS.		PLUG AND ANBANDONMENT	
PULL OR ALTER CASING				CASING TEST AND CEMENT JOB			
OTHER:				OTHER:			
12Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.							
Notify OCD 24 hrs. Be							

1. POH w/ rods & tubing
2. RIH open end to 2500 spot 100' plug from 2400 to 2500 woc & tag
3. Spot 100' plug from 975 to 1075' (salt 1025) Perforate 41/2" as a 1076' Squeeze cement look and Plug inside + Outside 41/2" as a 1076' Squeeze cement look and Plug inside + Outside 41/2" as a 1076' Squeeze cement look and Plug inside + Outside 41/2" as a 1076' Squeeze cement look and Plug inside + Outside 41/2" as a 1076' Squeeze cement look and Plug inside + Outside 41/2" as a 1076' Circulate cont from 30' to surface Perforate 41/2" as a 50' Circulate cont to surface - Inside + Outside 41/2" as a 1076' Circulate cont from 30' to surface.

6. Cut off well head install dry hole marker

# Brine well between cement Plug	ş,	
A Brine Gel between coment Plug. Notific N.M.O.C.D. to witness Plug	sing operations.	
nereby certify that the information above is true and complete to	the best of my knowledge and belief.	
GNATURE WAYLE COMME	TITLE Agent	DATE 03-23-01
		TELEPHONE NO. (915)580-7161
PE OR PRINT NAME Wayne Brooks		TELEPHONE NO. (913)360-7101
his space for State Use)		

APPROVED BY MILES WHILE

_ TITLE FICLURED. IL

DATE 3/73/7001

CONDITIONS OF APPROVAL, IF ANY: