FLM.O.C.D. COPY Form approved. Budget Bureau No. 42-R1424. Form 9-331 UINI 1ED STATES SUBMIT IN TRIPLICATE*
DEPARTMENT OF THE INTERIOR (Other instructions on reverse side) (May 1963) 5. LEASE DESIGNATION AND SERIAL NO. GEOLOGICAL SURVEY LC 069147 6. IF INDIAN, ALLOTTEE OR TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME OIL X FEB 0 9 1981 OTHER 2. NAME OF OPERATOR 8. FARM OR LEASE NAME Southland Royalty Company , $C_{i} \subset D_{i}$ Robinson Jackson Unit Tr 4 3. ADDRESS OF OPERATOR 1100 Wall Towers West; Midland, Texas 79701 #32 LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* Set also space 17 below.)

At surface 10. FIELD AND POOL, OR WILDCAT Jackson-Grayburg S.A. 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit Letter "C". 2310' FWL, 990' FNL Sec 34, T-17-S, R-29-E SEC 34, T-17-S, R-29-E 14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 12. COUNTY OR PARISH | 13. STATE 3517' GR Eddy New Mexico

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

16.

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:		
				[]		
TEST WATER SHUT-OFF		PULL OR ALTER CASING		WATER SHUT-OFF REPAIRING WELL		
FRACTURE TREAT		MULTIPLE COMPLETE	<u> </u>	FRACTURE TREATMENT ALTERING CASING		
SHOOT OR ACIDIZE		ABANDON*		SHOOTING OR ACIDIZING ABANDONMENT*		
REPAIR WELL		CHANGE PLANS		(Other) Correction of lease number X	ζ.	
(Other)				(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)		

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Please be advised that the following lease number, LC 028775 (a), was incorrectly indicated for the aforementioned lease on all commission forms. It should be corrected to LC 069147.

We sincerely appreciate the help of USGS & NMOCD in correcting our error.