Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

JST	
Form C-103	-
Revised 1-1-89	

DISTRICT I

OIL CONSERVATION DIVISION

DATE 8-22-89

P.O. Box 1980, Hobbs, NM 88240	REGEIVED P.O. Box 20)8 8	WELL API NO.
DISTRICT II	Santa Fe, New Mexico	87504-2088	30-015-24809
P.O. Drawer DD, Artesia, NM 88210 DISTRICT III	, ,		5. Indicate Type of Lease STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410	WIG 51 ,88		6. State Oil & Gas Lease No. LG953
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS FORM FOR PROPOSALS TO DRILLIANS TO DEEPEN OR PLUG BACK TO A			
DIFFERENT HESEF	RVOIR. USE APPLICATION FOR PE 101) FOR SUCH PROPOSALS.)	NOH PLOG BACK TO A :	7. Lease Name or Unit Agreement Name Gulf State
Type of Well: OIL GAS WELL X WELL	OTHER		Guil State
2. Name of Operator Beach Exploration,	Inc.,		8. Well No.
Address of Operator			9. Pool name or Wildcat
800 N. Marienfeld S	Suite 200 Midland, Tex	as 79701	Grayburg, Jackson, SR, QN, GB, SA
Unit Letter K : 231	O Feet From The South	Line and1650	O Feet From The West Line
Section 9	Township 17S R	ange 29E	NMPM Eddy County
	10. Elevation (Show whether		V/////////////////////////////////////
	3582.6 GL		
	Appropriate Box to Indicate		-
NOTICE OF INT	ENTION TO:	SUB	SEQUENT REPORT OF:
		İ	
RFORM REMEDIAL WORK	PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
	PLUG AND ABANDON X CHANGE PLANS	REMEDIAL WORK	
MPORARILY ABANDON			G OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON		COMMENCE DRILLING	G OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON	CHANGE PLANS	CASING TEST AND CE	G OPNS. PLUG AND ABANDONMENT
MPORARILY ABANDON LL OR ALTER CASING HER: Describe Proposed or Completed Operation work) SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, include	G OPNS. PLUG AND ABANDONMENT
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (ed.). Spot 25 Sx.	CHANGE PLANS Cons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, inclu follows:	G OPNS. PLUG AND ABANDONMENT
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (ed.). Spot 25 Sx. (plug 2399'	change Plans cons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049').	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, include follows: f. in San Andres	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing,
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (ed.). Spot 25 Sx. (plug 2399'	change Plans ons (Clearly state all pertinent details, and set. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399	COMMENCE DRILLING CASING TEST AND CE OTHER: and give pertinent dates, include follows: f. in San Andres	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing,
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (e. 1). Spot 25 Sx. (plug 2399' 2). Tag plug at 3). Load hole we 4). Spot 25 Sx.	change Plans ons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399 ith mud. plug from 750' - 350	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, included follows: f. in San Andres ', spot another ' (across surface)	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing,
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (e. 1). Spot 25 Sx. (plug 2399' 2). Tag plug at 3). Load hole w 4). Spot 25 Sx. 5). Spot 10 Sx.	change Plans ons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399 ith mud. plug from 750' - 350 plug from 125' to su	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, included follows: f. in San Andres ', spot another ' (across surface)	SOPNS. PLUG AND ABANDONMENT EMENT JOB ding estimated date of starting any proposed s) inside 4 1/2" casing, plug if necessary.
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (e. 1). Spot 25 Sx. (plug 2399' 2). Tag plug at 3). Load hole was 4). Spot 25 Sx. 5). Spot 10 Sx. 6). Install mar	change Plans ons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399 with mud. plug from 750' - 350 plug from 125' to su ker per requirements.	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, include follows: f. in San Andres ', spot another ' (across surface)	EMENT JOB ding estimated date of starting any proposed s) inside 4 1/2" casing, plug if necessary. ce casing shoe depth).
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (e. 1). Spot 25 Sx. (plug 2399' 2). Tag plug at 3). Load hole was 4). Spot 25 Sx. 5). Spot 10 Sx. 6). Install mar	change Plans ons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399 ith mud. plug from 750' - 350 plug from 125' to su	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, include follows: f. in San Andres ', spot another ' (across surface)	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing, plug if necessary. ce casing shoe depth).
Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (e. 1). Spot 25 Sx. (plug 2399' 2). Tag plug at 3). Load hole w. 4). Spot 25 Sx. 5). Spot 10 Sx. 6). Install mar 7). Remove all	ons (Clearly state all pertinent details, and st. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399 ith mud. plug from 750' - 350 plug from 125' to su ker per requirements. equipment, clean up 1 abandoned because it	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, include follows: f. in San Andres ', spot another ' (across surface, face, ocation as required)	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing, plug if necessary. ce casing shoe depth).
MPORARILY ABANDON LL OR ALTER CASING HER: Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (et al., 1). Spot 25 Sx. (plug 2399' 2). Tag plug at al., 2). Load hole with the spot 25 Sx. (plug 2399' 2). Tag plug at al., 2). Spot 10 Sx. (al., 2). Spot 10 Sx. (al., 2). Install mar al., 2). Remove all. This well is being low production rate	change Plans ons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399' ith mud. plug from 750' - 350 plug from 125' to suker per requirements. equipment, clean up 1 abandoned because it s.	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, included follows: f. in San Andres ', spot another ' (across surface, face, ocation as required) is uneconomical	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing, plug if necessary. ce casing shoe depth).
Plug and Abandon (e 1). Spot 25 Sx.	change Plans ons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399' ith mud. plug from 750' - 350 plug from 125' to suker per requirements. equipment, clean up 1 abandoned because it s.	COMMENCE DRILLING CASING TEST AND CE OTHER: Index pertinent dates, included follows: f. in San Andres ', spot another ' (across surface, included) contains a requirement of the contains and included included.	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing, plug if necessary. ce casing shoe depth). ired. to produce due to
MPORARILY ABANDON LL OR ALTER CASING HER: Describe Proposed or Completed Operation work) SEE RULE 1103. Plug and Abandon (et al., 1). Spot 25 Sx. (plug 2399' 2). Tag plug at al., 2). Load hole with the spot 25 Sx. (plug 2399' 2). Tag plug at al., 2). Spot 10 Sx. (al., 2). Spot 10 Sx. (al., 2). Install mar al., 2). Remove all. This well is being low production rate	change Plans ons (Clearly state all pertinent details, and est. date 9/15/89) as plug @2399' (top per - 2049'). least 50' above 2399' ith mud. plug from 750' - 350 plug from 125' to suker per requirements. equipment, clean up 1 abandoned because it s.	COMMENCE DRILLING CASING TEST AND CE OTHER: Ind give pertinent dates, included follows: f. in San Andres ', spot another ' (across surface, face, ocation as required) is uneconomical	EMENT JOB PLUG AND ABANDONMENT ding estimated date of starting any proposed s) inside 4 1/2" casing, plug if necessary. ce casing shoe depth).