

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DEC 22 1992

WELL API NO. 30-015-25077
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. E-742
7. Lease Name or Unit Agreement Name New Mexico "E0" State Comm
8. Well No. 1
9. Pool name or Wildcat South Empire Morrow Gas
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3637.60' G.R.

SUNDRY NOTICES AND REPORTS ON ~~WELLS~~ ~~OFF~~
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☐

GAS
WELL ☒

OTHER

2. Name of Operator

Mewbourne Oil Company

3. Address of Operator

P.O. Box 5270 Hobbs, New Mexico 88241

4. Well Location

Unit Letter E : 1980 Feet From The North Line and 660 Feet From The West Line

Section 20

Township 17S

Range 29E

NMPM

Eddy

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3637.60' G.R.

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 25 sx. plug at 8770'.
2. Set 5-1/2" CIBP @ - 8500'. Cap with 4 sx. cement.
3. Load hole with mud.
4. Cut 5-1/2" casing at + 1300'.
5. Spot 25 sx. plug at 7245'.
6. Spot 25 sx. plug at 5975'.
7. Spot 25 sx. plug at 5325'.
8. Spot 25 sx. plug at 3845'.
9. Spot 25 sx. plug at 3050'. Tag with tbg
10. Spot 25 sx. plug at 1705'. Tag with tbg.
11. Spot 35 sx. plug at 1350'.
12. Spot 35 sx. plug at 503'. Tag with tbg.
13. Spot 10 sx. plug at surface.
14. Install P & A marker & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Erick W. Nelson

TITLE

Engineer

DATE

12-18-92

TYPE OR PRINT NAME

Erick W. Nelson

TELEPHONE NO.

(505) 393-5905

(This space for State Use)

APPROVED BY

Mark A. Kelly

TITLE

DATE

DEC 23 1992

CONDITIONS OF APPROVAL IF ANY:

Notify N.M.O.C.C. in sufficient time to witness
SURRENDER

2
2
2
2

2
1

2
1
1

2
2
2
2
2