Form 3160–5 Jul y 1989) Formerly 9–331)	DEPART	UNI D ST MENT OF T	TATES THE INTERI	OFFICE FOR NUMP OF OOPLES REDUIN. (Other Instructions of verse side)	n	RIM Roswell DI Modified Form 1 NMD60-3160-4 FASE DESIGNATIO	No.	C
		AU OF LAND			1	4 0558263	N AND BREIAL	J NU.
SUN	DRY NO	TICES AND	REPORTS C	ON WELLS EIVED		INDIAN, ALLOTT	EE OR TRIBE	NAME
(Do not use this	form for prop	osals to drill or to	deepen or plug b	ack to a different reservoir.				
	Use "APPLIC	CATION FOR PERM	MIT—" for such pr	oposals.)		N/A		
OIL GAS WELL	OTHER	p	°&A	FEB 26 '90		TT AGREEMENT N	(A)(E	
. NAME OF OPERATOR		<u>+</u>		34. Area Code & Phor		N/A Em or lease na	ME	
YATES PETROLEUM CORPORATION				505/048-1471		Federal AA		
ADDRESS OF OPERATOR				ARTESIA, OFFICE		LL NO.		
105 South 4th	St., Art	esia, NM 8	8210			1		
. LOCATION OF WELL (Re See also space 17 belo At surface	w.)		Juance with kny .	State requirements.*		IELD AND POOL, (
660' FSL & 660' FEL, Sec. 27-T18S-R24E						Penasco Draw-SA-Yeso 11. SEC., T., R., M., OR BLK. AND		
	 ,		OD NEHL			SURVEY OR ARM.	A AND	
					Unit	P, Sec.	27-185-2	4F
4. PERMIT NO.		15. ELEVATIONS	(Show whether DF,	RT, GR, etc.)	12. c	OUNTY OB PABISE	H 13. STATE	
30-015-00148			3712' GR		Ed	dy	NM	
3.	Check A	ppropriate Box	To Indicate No	ature of Notice, Report,	or Other D)ata		
NO	DTICE OF INTER		P		BSEQUENT RE			
TEST WATER SHUT-OF	• 🗍	PULL OR ALTER CAS		WATER SHUT-OFF			[
FRACTURE TREAT		MULTIPLE COMPLET		FRACTURE TREATMENT		ALTERING C		
SHOOT OR ACIDIZE		ABANDON*	XX	SHOOTING OR ACIDIZING		ABANDONME		
					·		··· .	
REPAIR WELL		CHANGE PLANS		(Other)		·····		
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22	g well a: 64' w/50	s follows: ' cement ca	p.	(NOTE: Report re Completion or Red details, and give pertinent d ons and measured and true v	oupletion Re	port and Log fo	rm.)	; any perti-
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in	s follows: ' cement cap over Yeso an ' and pull. ' in and out	p. nd Glorieta t 8-5/8" &	(Norr: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones ;	; any perti-
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe	g well as 64' w/50 2020' (co at 1040 090' (50 e plug. ad and in and levo	s follows: ' cement cap over Yeso an ' and pull. ' in and out nstall dry l	p. nd Glorieta t 8-5/8" & hole marker	(Norr: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones ;	, any perti-
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa	s follows: ' cement cap over Yeso and ' and pull. ' in and out nstall dry h el. lt mud betwe	p. nd Glorieta t 8-5/8" & hole marker een them.	(Nork: Report re Completion or Red details, and give pertinent d ms and measured and true v a). Tag plug. 50' in and out of	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones ;	; any perti-
(Other) DESCRIBE PROPOSED OR O proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa	s follows: ' cement cap over Yeso and ' and pull. ' in and out nstall dry h el. lt mud betwe	p. nd Glorieta t 8-5/8" & hole marker een them.	(Nork: Report re Completion or Red details, and give pertinent d ms and measured and true v a). Tag plug. 50' in and out of	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones ;	; any perti-
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and our nstall dry H el. It mud betwo	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones ;	any perti-
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and our nstall dry H el. It mud betwo	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones p plug.	
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and our nstall dry H el. It mud betwo	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones p plug.	anyperti-
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and our nstall dry H el. It mud betwo	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones p plug.	
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and our nstall dry H el. It mud betwo	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and zones p plug.	
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and our nstall dry H el. It mud betwo	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and gones p plug.	
(Other) DESCRIBE PROPOSED OR (proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and our nstall dry H el. It mud betwo	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and gones p plug.	
(Other) DESCRIBE PROPOSED OR O proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA PLUGGING PROGR	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sal RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and out nstall dry H el. It mud betwo NM, 24 HOURS	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	ates, includir ertical depth	port and Log fo	rm.) ie of starting s and gones p plug.	
(Other) DESCRIBE PROPOSED OR O proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA PLUGGING PROGR	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sal RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and out nstall dry H el. It mud betwo NM, 24 HOURS	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC M, BLM, CAR	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING. LSBAD, NM.	$5\frac{1}{2}$ " stu	port and Log fo	rm.) ie of starting s and gones p plug.	
(Other) DESCRIBE PROPOSED OR O proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA PLUGGING PROGR	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sal RLSBAD, N	s follows: ' cement cap over Yeso and ' and pull. ' in and out nstall dry H el. It mud betwo NM, 24 HOURS	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC M, BLM, CAR	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING.	51" stu	port and Log fo	rm.) ie of starting s and zones p plug.	
(Other) DESCRIBE PROPOSED OR O proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA PLUGGING PROGR	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N AM APPROV	s follows: ' cement cap over Yeso and ' and pull. ' in and out nstall dry H el. It mud between WED PER ADAN VED PER ADAN	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC M, BLM, CAR	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING. LSBAD, NM.	51" stu	b). Tag p	rm.) ie of starting s and zones p plug.	
(Other) DESCRIBE PROPOSED OR of proposed work. If nent to this work.)* Propose to plu Set CIBP at 22 Set plug 1750- Cut off casing Set plug 880-1 Set 50' surfac Cut off wellhe Clean location All plugs will NOTIFY BLM, CA PLUGGING PROGR 1 hereby certify that the SIGNER And	g well as 64' w/50 2020' (cd at 1040 090' (50 e plug. ad and in and leve have sa RLSBAD, N AM APPROV	s follows: ' cement cap over Yeso and ' and pull. ' in and out nstall dry H el. It mud between WED PER ADAN VED PER ADAN	p. nd Glorieta t 8-5/8" & hole marker een them. S IN ADVANC M, BLM, CAR	(Nork: Report re Completion or Red details, and give pertinent d ons and measured and true v a). Tag plug. 50' in and out of E OF PLUGGING. LSBAD, NM.	5 ¹ / ₂ " stu	b). Tag p	rm.) ie of starting s and zones p plug. 90	

*See Instructions on Reverse Side