Form 9-331 (May 1963)

No. M. O. C. C. COPY TED STATES SUBMIT IN TR TED STATES SUBMIT IN TR (Other Instruct. verse side)

CATE*
on re-

_LC_062412

	GEOLOGICAL SC	SIK A C I		LC0 02412		
SUNDRY (Do not use this form Use	Y NOTICES AND RE for proposals to drill or to deep "APPLICATION FOR PERMIT-	PORTS (pen or plug t " for such p	ON WELLS ack to a different reservoir. roposals.)	6. IF INDIAN, ALLO	TTEE OR TRIBE NAME	
1. OIL CAS C				7. UNIT AGREEMENT	NAME	
WELL A WELL	OTHER		RECEIVE	D		
2. NAME OF OPERATOR				8. FARM OR LEASE	8. FARM OR LEASE NAME	
Atlantic RichfieldCompany NOV 1 2 1975					Empire Abo Unit "I"	
3. ADDRESS OF OPERATOR			1101 1 101 3	9. WELL NO.		
P. O. Box 1710, Hobbs, New Mexico 88240			18			
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements). C. See also space 17 below.) At surface ARTESIA, OFFICE			10. FIELD AND POOI	10. FIELD AND POOL, OR WILDCAT		
At surface			ACTESIA, OFFICE	Empire Ab		
		_		11. SEC., T., R., M., C SURVEY OR A		
660' FNL & 1980' FWL (Unit letter C)						
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			1 - 18S -			
AI, I BESTI NO.			RT, GR, etc.)	12. COUNTY OR PAR	ISH 13. STATE	
·		311' GR		Eddy	N.M.	
16. C	heck Appropriate Box To	Indicate N	ature of Notice, Report, or	Other Data		
	OF INTENTION TO:			QUENT REPORT OF:		
F				—		
TEST WATER SHUT-OFF	PULL OR ALTER CASING		WATER SHUT-OFF	REPAIRIN	G WELL	
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATMENT	ALTERING	CASING	
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ABANDON	MENT*	
REPAIR WELL	CHANGE PLANS O Gas Injection		(Other)	ts of multiple completion	on on Well -	
		<u></u>	Completion or Recom details, and give pertinent date ons and measured and true vert	IDBELLOR KENOTT BROLLOG	torm &	
TD 6173'. Present 8-5/8" OD 24# csg	perforations 5900- set @ 1515'. Cmtd	50', 2 w/1550	JSPF. sx. Circ to surface	e. NOV'	7 1975	
Approval No. PMX-6	5 under the provisi	ons of	Order No. 4549-B. R	ule 34 under	"Special	
Rules & Regulation	s for the Empire Ab	o Press	ure Maintenance pro	iect as follow	speciar	
1. Rig up, kill we	ell, install BOP & F	OH w/co	mpletion assv.	Jeet 25 10110#		
2. Set BP @ 4500',	run cmt bond log 4	500' to	TOC			
3. Set cmt retr ap	prox 40' above perf	s.		•		
4. Cmt thru perfs	w/HLW (vol to be de	t e rmine	d) $w/\frac{1}{4}$ # Flocele/sk.	followed by 2	00 sx C1 C	
Neat until cmt	circ, then pump Cl	C Neat	w/CaCl. If cmt does	s not circ, th	en run temp	
survey.						
5. Drill out & tes	t, remove BP @ 4500	٠٠.				
6. Set cmt retr @	5870' & squeeze per	fs 5900	-50' w/LWL cmt, fol:	lowed by Neat	cmt w/sd.	
7. Install high pr						
	5693-5700' w/l JSP					
9. Run internally	& externally plasti	c coate	d Lok-set°pkr & ER 1	receptacle w/l	.81 trim	
on $2-3/8$ OD in	ternally plastic co	ated the	7.			
10. Circ 4 d X 2-3/	8" annulus w/prod w	tr cont	g corrosion inhibit	tors.		
11. Set pkr @ 5560' csg-tbg annulus 18. I hereby certify that the fo	& connect up well (cont'd o	hd for n attac	gas injection. Inst ned Page #2)	tall pressure	gauge on	
SIGNED	d	TLED	ist. Drlg. Supv.	DATE 11/5	/75	
(This space for Federal or		rte bist	MOT EMOINEER	NOV	7 197 5	
CONDITIONS OF APPROV	AL, IF ANY:	, <u>, , , , , , , , , , , , , , , , , , </u>	200 C C C C C C C C C C C C C C C C C C	DATE	.07.3	


Form 9-331 Empire Abo Unit "I" #18 November 5, 1975 Page 2

- 12. Treat Abo perfs 5627-32' & 5693-5700' w/5000 gals 15% LSTNE acid using ball sealers to divert.
- 13. Swab back load to clean up & connect up for gas injection.

RECEIVED

NOV 7. 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO



RECEIVED

NOV 7 1975 U. S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

ATLANTIC RICHFIELD COMPANY Blow Out Preventer Program

Lease Name	Empire Abo Unit "I"
Well No.	18
Location	660' FNL & 1980' FWL
	Sec 1 T18S P27F Eddy Co

BOP to be tested before installed on well and will be maintained in good working condition during workover. All wellhead fittings to be of sufficient pressure to operate in a safe manner.