

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.
Santa Fe, NM 87505

WELL API NO.
30-015-00723

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
BP America Production Company

3. Address of Operator
P.O. Box 1089 Eunice, NM 88231

7. Lease Name or Unit Agreement Name
Empire Abo Unit "L"

8. Well No.
13

9. Pool name or Wildcat
Empire Abo

4. Well Location
Unit Letter M : 660 Feet From The S Line and 660 Feet From The W Line

Section 02 Township 18S Range 27E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: Workover ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD: 6075' PBD: 6075' PERFS: 5958-5968'

MIRUPU. NDWH. NUBOP. Drop SV to SN @ 5720'.
Chemically cut tbg above pkr. GIH w/overshot to top of fish.
Swab well down. Kill well if necessary. Catch fish.
RIH w/bit & scraper to PBTD. Perf w/2 JSPF 5770-5918'.
GIH w/RBP. Set @ +/- 5930'. Test plug. Spot 70 gals 15% HCL NEFE acid from
5918-5849'. PU and set pkr @ 5840. Acidize perfs w/2850 gals 15% HCL NEFE.
Displace w/25 bbls 2% KCL wtr. Rls pkr. PU and set @ 5840'. Test plug. Spot
70 gals 15% HCL NEFE acid from 5830-5761'. PU and set pkr @ 5740'. Acidize perfs
w/3050 gals 15% HCL NEFE. Displace w/25 bbls 2% KCL wtr. Rls pkr. Retrieve BP.
RIH w/production assy. NDBOP. NUWH. Swab for test. Return well to production.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 05.16.02

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505.394.1649

(This space for State Use)

**ORIGINAL SIGNED BY TIM W. GUM
DISTRICT II SUPERVISOR**

MAY 20 2002

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: