

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30015008183
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name West Red Lake
2. Name of Operator Hondo Oil & Gas Company ✓	8. Well No. 6
3. Address of Operator P. O. Box 2208, Roswell, NM 88202	9. Pool name or Wildcat Red Lake Qn-Grbg-SA

4. Well Location Unit Letter K : 2580 Feet From The West Line and 2460 Feet From The South Line Section 7 Township 18S Range 27E NMPM Eddy County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3294' GR
---	--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: Perf & Stimulate the lwr S.A. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- We would like to begin the following procedure 2/19/92.
- (1.) POH w/ rods & pump.
 - (2.) POH w/ tbg.
 - (3.) PU 3 7/8" bit DC's on 2 3/8" tbg & TIH.
 - (4.) Clean out 4 1/2" csg to 1770'.
 - (5.) POH & LD bit & DC's.
 - (6.) Run GR-CNL-CCL log from 1770'-700'.
 - (7.) Perf S.A. "C" zone from 1740'-1754' w/ 1 JSPF 15 holes.
 - (8.) TIH w/ pkr & acidize perfs 1740'-1754'.
 - (9.) Swab test.
 - (10.) Frac "C" zone perfs.
 - (11.) Clean out sd. fill.
 - (12.) Run pump & rods & test.

RECEIVED
FEB 17 1992
O. C. D.
ARTESIA OFFICE

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Karla LeJeune TITLE Petroleum Secretary DATE 02/13/92
TYPE OR PRINT NAME Karla LeJeune TELEPHONE NO. 625-6745

(This space for State Use) ORIGINAL SIGNED BY MIKE WILLIAMS DATE FEB 21 1992
APPROVED BY SUPERVISOR, DISTRICT II TITLE _____
CONDITIONS OF APPROVAL, IF ANY: _____