SANTA FE	NEW MEXICO OIL CONSE	福気で発射が位 なMMISSION	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65	
FILE	THE I MEXICO OIL CONSE	i additivi i from terio immoni oni ori		
U.S.G.S.			Sa. Indicate Type of Leas	а
LAND OFFICE	<u>-</u> Δ!	UG 25, 1980	State X	Fee [
OPERATOR			5, State Oil & Cas Lease	No.
1,1		O. V. W.		
SUND (00 NOT USE THIS FORM FOR P USE "APPLIC	DRY NOTICES AND REPORTS ON A			
OIL X GAS WELL	OTHER		7. Unit Agreement Name 8. Farm or Lease Name	
. Name of Operator Yates Drilling (Company /			.i.+
. Address of Operator			Artesia Metex Un	.± L
	-1'- 274 00230		#6	
Location of Well	rtesia, NM 88210		10. Field and Pool, or Wi	lden!
	16501	22101		
UNIT LETTER K	1650 FEET FROM THE South	_ LINE AND Z31U FEET FRO	" TITTITITITITITITITITITITITITITITITITIT	mm
THE West LINE, SEC	TION 24 TOWNSHIP 18S	RANGE 27E NMPA		
	15. Elevation (Show whether D *3557 GR	F, RT, GR, etc.)	12. County Eddy	
Check	k Appropriate Box To Indicate Na	sture of Notice, Report or O	ther Data	
	INTENTION TO:	-	IT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASI	=
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ASAN	ONMENT []
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JQB	.ct	X
		OTHER Bradenhead Te	St.	<u> </u>
OTHER				
7. Describe Proposed or Completed work) SEE RULE 1103.	Operations (Glearly state all pertinent detail	ls, and give pertinent dates, including	ng estimated date of starting	any proposed
pressure 2" val	above ground level. Insta- ve. Swidged down w/ tapped	ball plug - to ½" need		
hradanhand and	casing shut in 24 hours 1			
		ing managering 11E01 T	inancation but	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on	bradenhead or casing. Tub:	ing pressure 1150'. I	inspected by	
No pressure on Mr. Weaver, OCD,	bradenhead or casing. Tub: Artesia.		inspected by	
No pressure on Mr. Weaver, OCD,	bradenhead or casing. Tub:		inspected by	
No pressure on Mr. Weaver, OCD,	bradenhead or casing. Tub: Artesia.		inspected by	1080