

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	

**RECEIVED**

NEW MEXICO OIL CONSERVATION COMMISSION  
JUN 21 1976

**O. C. C.**  
**ARTESIA, OFFICE**

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-1821
7. Unit Agreement Name
8. Farm or Lease Name Powell State
9. Well No. 1
10. Field and Pool, or Wildcat Art, Qn, Gbr. S.A.
12. County Eddy

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator MURPHY MINERALS CORPORATION
3. Address of Operator P. O. Box 2164, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER M 330 FEET FROM THE S LINE AND 330 FEET FROM THE W LINE, SECTION 17 TOWNSHIP 18S RANGE 28E NMPM.
15. Elevation (Show whether DF, RT, CR, etc.) Unknown

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

8 5/8", 32# csg. @ 439' with 50 sx.  
4 1/2", csg. @ 2323' with 50 sx. T.D. 2390' Open hole 2323-2390'.  
PROGRAM-25 lb. gel/bbl. between all plugs.  
1) Spot 100' (min. 20 sx) plug from 2273' to 2373'.  
2) Shoot off 4 1/2" csg.  
3) Spot 100' plug across stub of 4 1/2" csg.  
4) Spot 100' plug across shoe of 8 5/8" csg.  
5) Set 25' plug and surface marker.  
6) Clean up location.

The New Mexico Oil Conservation Commission will be notified in sufficient time to witness plugging.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED T. M. Boyd TITLE Agent DATE 6/18/76  
APPROVED BY W. A. Gressett TITLE SUPERVISOR, DISTRICT II DATE JUN 21 1976

CONDITIONS OF APPROVAL, IF ANY:

Spot a 100' Plug over Queen from 1400-1500' if 4 1/2" comes below this point