

Jim's Water Service of New Mexico

A Division of Jim's Water Service of Colorado, Inc.

P. O. Box 848
Artesia, New Mexico 88210
(505) 748-1352
(505) 622-9790

M-19609 State 24 Well 1
Completion Report

Follow up report and results of report C-103 dated 9-28-92.

September 29, Tuesday

Rig up. Attempt to pull tubing. Tubing stuck, pull 30,000 lbs, and work stuck tubing. Rig up pump truck on tubing. Pumped 4 lbs. per minute. Work stuck tubing. Pull 60,000 lbs on tubing. Tubing pulled free. Pulled with 5-10 points drag. Recovered 14 joints plus 8 feet.

Pick up 4 3/4 bit, welded on 2 7/8 EVE collar. Started in hole. Tagged up at 410. Picked up swivel, started drilling anhydrite stringers at 410-418, 520-550. Cleaned out to 610 feet. Circulated hole. Rig down swivel. Lard well at 602 = 19 joints. Restored back to production.