

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO.  
30-015-02622

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
ARCO Permian

3. Address of Operator  
P.O. Box 1089 Eunice, NM 88231

4. Well Location  
Unit Letter L : 2219.18 Feet From The S Line and 660 Feet From The W Line

Section 6 Township 18S Range 28E NMPM Eddy County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)  
RDB 3644'

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐  
OTHER: Workover ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
CASING TEST AND CEMENT JOB ☐  
OTHER: ☐

12. Describe Proposed or Completed Operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

MIRUPU. POH w/rods & pmp. NDWH. NUBOP. RIs TAC POH w/tbg & TAC  
RIH w/4-3/4" bit & scraper to 6177'. POH. RU Wireline. Run Gamma Ray Correlation Log.  
GIH w/CIBP. Set @ 6100' +/- based on collar locations. POH. GIH & perf w/2 JSPF 5792 to 5796,  
5800 to 5804, 5812 to 5818, 5826 to 5829, 5836 to 5840, 5848 to 5852, 5860 to 5870, 5878 to 5886,  
5905 to 5908, 5912 to 5921, 5943 to 5996, 5988 to 6014, and 6042 to 6068. POH. GIH w/treating pkr  
& 2-3/8" tbg. Spot 300 gals 15% HCL NEFE from 6068-5768'. Pull up set PKR @ 5740' +/- . Acidize  
perfs w/3600 gals 15% HCL NEFE. Displace w/30 bbls 2% KCL fresh wtr. POH w/tbg & pkr. RU Wireline.  
RIH and knock CIBP @ 6100 +/- to bottom. Est. 6173'. POH. RIH w/bull plugged MA, perf sub, API SN  
& 2-3/8" tbg. Land SN @ +/- 6140'. NDBOP. NUWH. Swab for test. RIH w/GA, pmp, & rods. RDPU. RTP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kellie D. Murrish TITLE Sr. Administrative Assistant DATE 08/23/01

TYPE OR PRINT NAME Kellie D. Murrish TELEPHONE NO. 505-394-1649

(This space for State Use)

ORIGINAL SIGNED BY TIM W. GUM  
DISTRICT II SUPERVISOR

AUG 29 2001

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: