			N.M. CII CUI	Division CIG
rm 3160-5	UNITE	ED STATES	311 S. 1st 51	FORM APPROVED
ne 1990)	DEPARTMENT OF THE INTERIOR		Ar.esia, NM	0-28 Burget Bureau No. 1004-0135 Expires: March 31, 1993
		ND MANAGEMENT	AL 9512, 19.4	5. Lease Designation and Serial No.
	BOREAU OF EF			•
	SUNDRY NOTICES A	ND REPORTS ON WE	LLS .	LC-060905 6. If Indian, Allottee or Tribe Name
Do not use this fo U	rm for proposals to drill se "APPLICATION FOR	or to deepen or reentry	to a different reservoir.	
	SUBMIT I	N TRIPLICATE		7. If Unit or CA, Agreement Designation
Type of Well	·····		11911	
X Oil Gas Well Well	Other	l.S.	NUV :	8. Well Name and No.
Name of Operator			and a state of the	WLHU G4S Tract 14-2
YATES PETROLEUM CORPORATION (505) 748-1471)				9. API Well No.
Address and Telephone No.				30-015-03229
105 South 4th St., Artesia, NM 88210			10. Field and Pool, or Exploratory Area	
Location of Well (Footage, Sec., T., R., M., or Survey Description)				Loco Hills-Queen-GB-SA
990' FSL & 990' FEL of Section 1-T18S-R29E (Unit P, SESE)				11. County or Parish, State
990' FSL & 9	90' FEL of Section	1-1185-R29E (Unit	r, SESE)	
	•	·		Eddy Co., NM
CHECK /	APPROPRIATE BOX(s)	TO INDICATE NATUR	RE OF NOTICE, REPO	DRT, OR OTHER DATA
	SUBMISSION		TYPE OF ACTION	
				·
X Notice of	f Intent		t	Change of Plans
-			1	New Construction
	ent Report	Plugging Bac	:k	Non-Routine Fracturing
		Casing Repai	ir	Water Shut-Off
Final Ab	andonment Notice	Altering Casi	ine	Conversion to Injection
			D	in the second se
		X Other Tem	porary Abandon	Dispose Water
	mpleted Operations (Clearly state all p tions and measured and true vertical	ertinent details, and give pertinent dat	porary Abandon	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
give subsurface local Propose to t the offset w 1. TOOH wit 2. TIH with go due to pa and corrosic 3. Install psi for 30 m 4. If well	tions and measured and true vertical temporarily abandor wells that are to h th pump, rods and t n wireline gauge ri- araffin, attempt tu on inhibitor. 2" valve on pup jo minutes. fails casing integ	ertinent details, and give pertinent dat depths for all markers and zones per h this well for a p be deepened. Work tubing. ing to 2650'. Wire ubing set CIBP. Wi point in packed off grity test, procedu	porary Abandon tes, including estimated date of starti- rtinent to this work.)* beriod of one (1) will be done as f eline set CIBP at ith plug set, load wellhead. Pressu ire will be issued	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled, year, in order to observe follows: 2650'. If CIBP will not I casing with 2% KCL water are test casing to 500 I to plug and abandon well
give subsurface local Propose to t the offset w 1. TOOH wit 2. TIH with go due to pa and corrosic 3. Install psi for 30 m 4. If well	tions and measured and true vertical temporarily abandor wells that are to h th pump, rods and t a wireline gauge ri- araffin, attempt tu on inhibitor. 2" valve on pup jo ninutes. fails casing integ	ertinent details, and give pertinent dat depths for all markers and zones per h this well for a p be deepened. Work tubing. ing to 2650'. Wire ubing set CIBP. Wi point in packed off grity test, procedu	porary Abandon tes, including estimated date of starti- rtinent to this work.)* beriod of one (1) will be done as f eline set CIBP at ith plug set, load wellhead. Pressu ire will be issued	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled year, in order to observe ollows: 2650'. If CIBP will not I casing with 2% KCL water are test casing to 500
give subsurface local Propose to t the offset w 1. TOOH wit 2. TIH with go due to pa and corrosic 3. Install psi for 30 m 4. If well NOTIFY OCD-A CASING INTEC	tions and measured and true vertical temporarily abandor wells that are to h th pump, rods and t a wireline gauge ri- araffin, attempt tu on inhibitor. 2" valve on pup jon ninutes. fails casing integ ARTESIA (748-1283) GRITY TEST	ertinent details, and give pertinent dat depths for all markers and zones per h this well for a p be deepened. Work tubing. ing to 2650'. Wire ubing set CIBP. Wi point in packed off grity test, procedu	porary Abandon tes, including estimated date of starti- rtinent to this work.)* beriod of one (1) will be done as f eline set CIBP at ith plug set, load wellhead. Pressu ire will be issued	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled, year, in order to observe follows: 2650'. If CIBP will not I casing with 2% KCL water are test casing to 500 I to plug and abandon well
give subsurface local Propose to t the offset w 1. TOOH wit 2. TIH with go due to pa and corrosic 3. Install psi for 30 m 4. If well NOTIFY OCD-A CASING INTEC	tions and measured and true vertical temporarily abandor wells that are to h th pump, rods and t a wireline gauge ri- araffin, attempt tu on inhibitor. 2" valve on pup jo ninutes. fails casing integ	ertinent details, and give pertinent data depths for all markers and zones per n this well for a p be deepened. Work tubing. ling to 2650'. Wire abing set CIBP. Wi point in packed off grity test, procedu AND BLM-CARLSBAD	porary Abandon tes, including estimated date of starti- rtinent to this work.)* beriod of one (1) will be done as f eline set CIBP at ith plug set, load wellhead. Pressu ire will be issued	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled year, in order to observe follows: 2650'. If CIBP will not I casing with 2% KCL water are test casing to 500 I to plug and abandon well
give subsurface local Propose to t the offset w 1. TOOH with 2. TIH with go due to pa and corrosic 3. Install psi for 30 m 4. If well NOTIFY OCD-A CASING INTEC	tions and measured and true vertical temporarily abandor wells that are to h th pump, rods and t n wireline gauge ri- araffin, attempt tu on inhibitor. 2" valve on pup jon ninutes. fails casing integ ARTESIA (748-1283) GRITY TEST	ertinent details, and give pertinent dat depths for all markers and zones per h this well for a p be deepened. Work tubing. Ing to 2650'. Wire ubing set CIBP. Wi point in packed off grity test, procedu AND BLM-CARLSBAD	porary Abandon tes, including estimated date of starti- rtinent to this work.)* beriod of one (1) will be done as f eline set CIBP at ith plug set, load wellhead. Pressu ire will be issued (887-6544) IN ADVA	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled year, in order to observe follows: 2650'. If CIBP will not I casing with 2% KCL water are test casing to 500 I to plug and abandon well ANCE TIME TO WITNESS
give subsurface local Propose to t the offset w 1. TOOH with 2. TIH with go due to pa and corrosic 3. Install psi for 30 m 4. If well NOTIFY OCD-A CASING INTEC	tions and measured and true vertical temporarily abandor wells that are to h th pump, rods and t n wireline gauge ri- araffin, attempt tu on inhibitor. 2" valve on pup jon ninutes. fails casing integ ARTESIA (748-1283) GRITY TEST	ertinent details, and give pertinent dat depths for all markers and zones per h this well for a p be deepened. Work tubing. Ing to 2650'. Wire ubing set CIBP. Wi point in packed off grity test, procedu AND BLM-CARLSBAD	porary Abandon tes, including estimated date of startin rtinent to this work.)* period of one (1) will be done as f eline set CIBP at ith plug set, load wellhead. Pressu ire will be issued (887-6544) IN ADVA ms Technician	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled year, in order to observe ollows: 2650'. If CIBP will not I casing with 2% KCL water are test casing to 500 500 I to plug and abandon well ANCE TIME TO WITNESS
give subsurface local Propose to t the offset w 1. TOOH witt 2. TIH with go due to pa and corrosic 3. Install psi for 30 m 4. If well NOTIFY OCD-A CASING INTEC	tions and measured and true vertical temporarily abandor wells that are to h th pump, rods and th n wireline gauge ri- araffin, attempt to on inhibitor. 2" valve on pup jo ninutes. fails casing integ ARTESIA (748-1283) GRITY TEST	ertinent details, and give pertinent dat depths for all markers and zones per h this well for a p be deepened. Work tubing. Ing to 2650'. Wire ubing set CIBP. Wi point in packed off grity test, procedu AND BLM-CARLSBAD	porary Abandon tes, including estimated date of starti rtinent to this work.)* beriod of one (1) will be done as f eline set CIBP at ith plug set, load wellhead. Pressu ire will be issued (887-6544) IN ADVA	Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form) ing any proposed work. If well is directionally drilled year, in order to observe collows: 2650'. If CIBP will not I casing with 2% KCL water are test casing to 500 I to plug and abandon well ANCE TIME TO WITNESS Date Oct. 9, 1997