

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

RECEIVED

JUN 3 1974

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

O. C. C.

ARTESIA OFFICE

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name Ballard Grayburg San Andres Unit
2. Name of Operator Anadarko Production Company	8. Farm or Lease Name Tract No. 23
3. Address of Operator P. O. Box 67, Loco Hills, New Mexico 88255	9. Well No. 1
4. Location of Well UNIT LETTER L 2310 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 5 TOWNSHIP 18 S RANGE 29 E NMPM.	10. Field and Pool, or Wildcat Loco Hills Queen Grayburg San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 3577 DF	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JGB ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Spot 100 sx cement plug in open hole from 2712' to 2490'.
2. Shut down 4 hours, wait on cement, tag plug.
3. Spot 100 sx cement plug in open hole from 2490' to 2319' & in bottom of 7" csg. from 2319' to 2270'.
4. Circulate hole with mud laden fluid.
5. Shoot off 7" casing @ base of salt. (approx. 750')
6. Pull 7" casing.
7. Spot 35 sx cement plug 50' in and 50' out of casing @ base of salt.
8. Spot 35 sx cement plug 50' in and 50' out of 8 5/8" surface csg. @ 344'.
9. Spot 10 sx cement plug at surface.
10. Erect dry hole marker & clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signed by

SIGNED

Area Supervisor

TITLE

DATE

May 30, 1974

APPROVED BY

TITLE

OIL AND GAS INSPECTOR

DATE

JUN 3 1974

CONDITIONS OF APPROVAL, IF ANY: Notify N.M.O.C.C. in sufficient time to witness

Plugging