- ·		.,	-	
Submit 3 Copies to Appropriate District Office State of New M Minerals and Natural R	· · · · ·	C151	Form C-103 Revised 1-1-89	
DISTRICT I P.O. Box 1980, Hobbs, NM 88240 OIL CONSERVATION DIVISION P.O. Box 2088		WELL API NO.	027.00	
DISTRICT II P.O. Drawer DD, Artesia, NM 88210 Santa Fe, New Mexico 87504-2088		30 - 0/5 - 5. Indicate Type of Lease		
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		6. State Oil & Gas Lease N	TATE X FEE	
		E-1819		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Ag	reement Name	
1. Type of Well: OIL GAS WELL X WELL COTHER		State P		
Name of Operator		8. Weil No.		
Elliott OIl Company		#1		
3. Address of Operator		9. Pool name or Wildcat		
P.O. Box 1355 Roswell, NM 88202-1355 4. Well Location		Turkey Track		
Unit Letter H: 1980 Feet From The N	Line and 330	Feet From The _	E Line	
Section 36 Township 18 S	Range 29 E	NMPM Eddy	County	
10. Elevation (Show wheth	r DF, RKB, RT, GR, etc.)	V///		
(//////////////////////////////////////				
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON X			RING CASING	
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING CASING TEST AND C		EMENT JOB		
OTHER:	OTHER:	OTHER:		
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.				
Operator proposes to plug and abandon the above well as follows:				
1.) Pull tubing and rids and set CIBP @ 2430 ' and cap with 50' of cement 2.) Cir hole with 25# mud 2683' 7. Perf. : 2783 .				
-3) Set coment plug @ (base of salt 1135') 1190' 100 ft plug to 1090'				
4.) Perf casing and place 100 ft. of cement on retainer				
5.) Set cement plug @ 60' to surface				
6.) Cut off well head and set dry hole marker				
7.) Cut off anchors and clean up location				
* Perforate 51/2" csq > 1190: Squeeze 100' cement Plus incide + outside 51/2" esg. 774 Styles 200				
* 100 rement Plug inside + outside 51/2" csg from 419-319. TAG				
* Natifie N.M.O.C.D. to witness Plagging Operations.				
I hereby certify that the information above a price and complete to the beauti my knowledge	and belief.			
SIGNATURE SIGNATURE	mme Agent	:	DATE 7/29/89	
YPEORPRINT NAME Donald G. Becker, Jr.			TELEPHONE NO.	
is space for State Use)				
TED BY Misel Stulk field	TITLE FIELD Rep. II		DATE 8/3/99	

ONS OF APPROVAL, IF ANY: