

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
SUBMIT IN TRIPL
(Other Instructions
Ltr 100-0100)
COMMISSION
Drawer ID
Artesia, N.M. 88210

Expires August 31, 1985
5. LEASE DESIGNATION AND SERIAL NO.

LC-062029

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☒ WIW	RECEIVED BY MAY 01 1986 O. C. D. ARTESIA, OFFICE	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR Marbob Energy Corporation ✓		8. FARM OR LEASE NAME Brainard Tr. 4	
3. ADDRESS OF OPERATOR P.O. Drawer 217, Artesia, N.M. 88210		9. WELL NO. 10	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1325 FSL 2645 FWL		10. FIELD AND POOL, OR WILDCAT Turkey Track SR On Grbg 11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 34-T18S-R29E	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3410' GR	12. COUNTY OR PARISH Eddy	13. STATE N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon as follows: Set cement plug from 2140' to 1750'; tag; shoot casing off @ 1500'; set 100' plug in and out of stub; tag; set 100' plug @ 1020' to 920'; tag; cover base of salt; set 100' plug top of salt & shoe of 8 5/8" in and out of shoe; tag; set 50' plug @ surface; install dry hole marker.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Production Clerk

DATE

4/23/86

(This space for Federal or State office use)

APPROVED BY


TITLE

DATE

4-29-86

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



COMPANY Marbob Energy
LEASE & WELL NO. BRANARD #10
FORMATION _____
COUNTY & STATE _____



Robert C. Chase
Completion Supervisor

(505) 748-3303

P. O. Drawer 217
Artesia, N.M.
88211-0217

marbob
energy corporation

Proposal

P&A AS FOLLOWS:

Set 100' Plug @ 2100' Tag

Run Free Point Shot casing

off @ 1600' set 100' Plug

50' in & out of stub Tag

Set 100' Plug @ 1020' Tag

set 100' Plug @ 420' Tag

15sx Plug @ surface

S/O 2111-13

S/O 2119-37

8 5/8 20" @ 370' C/100 SAX

Top Salt 354

Base Salt 965

Top 7 Rivers 1200'

Top Queen 1800'

Perfs 2132-36

4 shot @ 2123

FRAC 4000 gals

4 1/2 9.5" @ 2148 C/130 SAX

100% 1428'

90% 1644'

1644
-1428
216

1644
-1000
1544

TD 2168