COMMISSION BUREAU OF LAND MANAGEMENT	OFFICE FOR NAME OFFICE FOR NAME OF COPIES RECU (Other Instruction is re- verse alde)	Hodified Form No. CIST NHX60-3160-4 3. LEARE DESIGNATION AND BERIAL NO.
BUREAU OF LAND MANAGEMENT BUREAU OF LAND MANAGEMENT MARKEN POPULATION FOR PERMIT—" for auch prop Use "APPLICATION FOR PERMIT—" for auch prop	N WELLS	C. O47269A 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
I. OIL CAR GAR OTHER Convert to producing		7. UNIT AGREEMENT NAME West Loco Hills G4S Unit
2. NAME OF OPERATOR YATES PETROLEUM CORPORATION	3a. Area Code & Phone No. 505/748-1471	8. FARM OR LEASE NAME Tract 1
3. ADDRESS OF OPERATOR		9. WHIL NO. Well 8
105 South 4th St., Artesia, NM 88210 4. LOCATION OF WELL (Report location clearly and in accordance with any St See also space 17 below.) At surface	ate requirements.* RECEIVED	10. FIELD AND FOOL, OR WILDCAT LOCO HIIIS-Q-G-SA
2310' FNL & 330' FWL, Sec. 7-185-30E	MAR 1 3 100+	11. SBC, T., B., M., OR BLK. AND SURVEY OR ABBA Unit E, Sec. 7-T18S-R30E
1-1. PERMIT NO.	T. GR. CL. D. C. D.	12. COUNTY OF PARISE 13. STATE Eddy NM
16. Check Appropriate Box To Indicate Nat		ther Data
NOTICE OF INTENTION TO :	\$1738EQU	BNT REPORT OF:
TEST WATER SHUT-OFF PULL OR ALTER CASING	WATER SHOT-OFF	REPAIRING WELL
PRACTURE TREAT MULTIPLE COMPLETE	SHOOTING OR ACIDIZING	ALTERING CASING
BEPAIR WELL CHANGE PLANS	(Other)	
(Other)	(Nors: Report results Completion or Recomple	of multiple completion on Well etion Report and Log form.)
and tools. Run CBL from 2774 to surface. If top of salt, then squeezes must be performed. Notifiy Mike Williams, OCD, of this informati above or below salt w/4 squeeze holes, run paretainer and squeeze w/50 sx Class C Salt sat pumped at low rates. Precede tail in cement WOC 24 hrs (at least) and drill out retainers J-55 casing with packer type casing shoe and circulation w/fresh water mud (±100 bbls) and 200 sx Lite wt Poz (1.88ft ³ /sx) and 100 sx CD Drill out casing shoe w/3-3/4" bit and clean bottom. Probably one slip and one drag spring RIH w/tubing and decentralized Hydra-jet tool NEFE acid. POOH w/tools and tubing. RIH w/t necessary. Run pump and rods to ±2770' and p	B. of salt - 1105' on. If no cement is ocker and establish is urated cement and 50 w/5 bbls of Flochek. to 2774'. POH w/tu centralizers to ±277 cement w/(500ft ³ of ass C w/2% CaCl2 (1. out open hole to 283 g. Also, TD may be 28 L. Acidize and jet of cubing and SN. Check	; T. of salt - 392'. s indicated, perforate ± 50' injection rate, run cement) sx Class C w/2% CaCl2 If squeezes are performed, abing and tools. Run 4½" 9.5 70 and set. Establish f cement-50% excess) ie .32 ft ³ /sx). WOC 48 hrs. L4'. Note: Junk in hole on 821'. POOH w/tubing and bit. open hole w/3000 gals 15% k for fill. Clean out, if
19. 1 hereby certify that the foregoing is true and correct SIGNER (Linet A bodiet) TITLE Prod (This space for Federal or State office use)	uction Supervisor	DATE
	ETROLE . W ENCINEER	3/12/91
CONDITIONS OF APPROVAL, IF ANY :		LARY TE

11. 11.

*See Instructions on Reverse Side