16.

LICATE. SUBMIT IN DEPARTMENT OF THE INTERIOR (Other instructions on reverse side)

Form approved. Budget Bureau No. 42-R1424 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

, , , ,	1121	4 V	

							_
SUNDRY	NOTICES	AND	REPOR	RTS	ON	WELLS	

Do not	use	this	form	for	proposals	to drill	or	to	decpen	or	plug	back	to a	different reservoir.
			Use	"Al	PLICATIO	N FOR	PE	:KM	11	IOL	sucn	propo	sais.	-

GEOLOGICAL SURVEY

1.	OIL GAS OTHER WIW - TA	RECEIVED	BW. L. H. U. GRB	#4 SD UT
2.	NAME OF OPERATOR NEWMONT OIL COMPANY	NOV 28 198		E
	P. O. BOX 1305 ARTESIA. N.M. 882	O. C. D.	9. WELLING.	
4.	LOCATION OF WELL (Report location clearly and in accordance with any State red See also space 17 below.) At surface	ulfelmente.	10. FIEED AND POOL, OR LOCO HILLS 11. SEC., T., R., M., OR B SURVEY OR AREA	Q.G.SAl
	330' FSL, 990 FEL Sec. 7-18-30		Sec. 7-18-	30
14	PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, 6	tc.)	12. COUNTY OR PARISH	13. STATE
	3524'		Eddy	New Mexi

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

		· · · · · · · · · · · · · · · · · · ·					
NOT	ICE OF I	NTENTION TO:	SUBSEQUENT REPORT OF:				
TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL (Other)		PULL OR ALTER CASING MULTIPLE COMPLETE ABANDON* CHANGE PLANS		WATER SHUT-OFF FRACTURE TREATMENT SHOOTING OR ACIDIZING (Other) (Note: Report resu Completion or Reco	ilts comple	REPAIRING WELL ALTERING CASING ABANDONMENT* f multiple completion on Well tion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) *

Plugged and abandoned well as follows.....


12/27/82....Set CIBP @ 2740'. Capped with 25 sacks cement. Perf 4 shots @ 1158'.

12/28/82.... Squeezed 50 sacks @ 1158'. Squeezed @ 1000 psi.

12/29/82....Tagged plug at 1050'. Perf 4 shots @ 430'. Bullhead squeezed 100 sacks.

12/30/82....Tagged plug at 190'. Pressured to 500 psi. Set 15 sack top hole plug and P&A marker.

Location ready for inspection



DATE

TITLE . This times for Feller

APPROVED BY CONDITIONS OF APPROVAL, IF ANY: