

From

W. A. GRESSETT Supervisor

Do Texaco, Inc.

We did not receive a C-104 showing change on your McClay Federal #2-H, 33-18S-30E.

Please advise if this well was supposed to be included in this unit or not.