

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
Artesia, NM 88210

TE
re

Budget Bureau No. 1004-0135
Expires August 31, 1985

clsf

5. LEASE DESIGNATION AND SERIAL NO.

LC-028978-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Texaco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 728, Hobbs, N.M. 88241 D.

4. LOCATION OF WELL (Report location clearly and in accordance with any special requirements.
See also space 17 below.)
At surface

Unit Ltr. C
660' FNL 1980' FWL

RECEIVED BY

NOV 25 1985

7. UNIT AGREEMENT NAME

North Benson Queen Unit

8. FARM OR LEASE NAME

9. WELL NO.

36

10. FIELD AND POOL, OR WILDCAT

North Benson Queen Gray-
Burg

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 34 T18S R30E

12. COUNTY OR PARISH 13. STATE

Eddy

N.M.

14. PERMIT NO.

30-015-04561

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3460' DF 3459 GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other) Calcium Scale Treatment

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRUPU. Pull rods and pump. Install BOP. Pull tbgs.
2. TIH W/ bit and clean to TD 3406'. TOH.
3. TIH W/ Pkr. and workstring.
4. Spot scale converter across perfs and OH, 2827-3406'. SI 18 Hrs.
5. Circulate hole clean, pull pkr. to 2750' and set.
6. Treat as follows:
 - a) pump 1/2 drum inhibitor w/ 10 BW, flush w/ 10 BW
 - b) pump 500 gal. 15% NEFE
 - c) drop 500# rock salt in gelled brine, flushed w/ 10 BW
 - d) repeat steps a & b, overflushed w/ 50 BW. SI 1 Hr.
7. TOH w/ pkr.
8. TIH w/ tbgs. Break down BOP. TIH w/ pump and rods.
9. RDPU. POB and test well.

BDB

I hereby certify that the foregoing is true and correct

SIGNED

W.B. Galt

TITLE Dist. Opr. Mgr.

DATE 11-13-85

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE 11-22-85

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side