

Form 9-331
(May 1963)UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN 1 (Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC-028978-B

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☐ OTHER ☐	Injection Well		RECEIVED	7. UNIT AGREEMENT NAME North Benson Queen Unit
2. NAME OF OPERATOR TEXACO INC.	NOV - 7 1973		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR P. O. Box 728, Hobbs, New Mexico 88240	O. C. C.		9. WELL NO. 39	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 1650' FWL and 1980' FWL of Sec. 34, T-18-S, R-30-E, Unit Letter F	ARTESIA, OFFICE		10. FIELD AND POOL, OR WILDCAT North Benson Queen Grayburg	
14. PERMIT NO. Regular	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3460' GR	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T-18-S, R-30-E		
		12. COUNTY OR PARISH Eddy	13. STATE N.M.	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐

(Other) Convert to Injection

PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☐REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rods and pump, check TD w/tubing and pull tubing.
2. Clean out to TD if necessary.
3. Perforate 4-1/2" casing w/2 JSPP @ 2855-60 and 3064, 71, and 3078.
4. Run tubing, packer and RBP, selectively straddle, acidize each set of perfs w/500 gals. 3% HF and 12% HCL acid.
5. Frac each set of perfs w/10,000 gals. GPM in 5 equal stages, flush w/1500 gals. gelled brine water, separate stages w/400# rock salt.
6. Pull tubing, packer and RBP.
7. Run plastic coated 2-3/8" tubing w/packer set @ 2800'.
8. Connect up for injection.
9. Load annulus w/inhibited water.
10. Run injectivity profile when pressure and injection rate have stabilized.

NMOCC Order No. R-4537

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Asst. Dist. Supt.

DATE

NOV 2 1973

(This space for Federal or State office use)

TITLE

DATE

APPROVED

NOV 6-1973

R. L. BECKMAN
ACTING DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.