IN. M. U. U. C. CUPY

U ED STATES SUBMIT IN TRIF (Other Instructio verse side) U TED STATES

GEOLOGICAL SURVEY

TE*

LC-058650

				6. IF INDIAN, ALLOTTEE	OR TRIBE NAME	
SUNDRY NOTI	CES AND REPORTS	ON WELLS				
(Do not use this form for propose Use "APPLICA"	ils to drill or to deepen or plug	back to a different	t reservoir.	b -		
Use "APPLICA	TION FOR FERMIT— Tot such	proposality E C		7. UNIT AGREEMENT NAM	ME	
1. OIL TO GAS				Month Pongon	Oncor The	: 4
WELL A WELL OTHER		JUL	<u>. 2 1 1976 </u>	North Benson		LU
2. NAME OF OPERATOR				· ·		. ,
TEXACO Inc.			,	North Benson	- Queen Uni	LT
3. ADDRESS OF OPERATOR			J. Li. Li.	9. WELL NO.		
P. O. Box 728, Hob	bs. New Mexico {	38240 ARTE	SIA, OFFICE	38		
4. LOCATION OF WELL (Report location cl	early and in accordance with ar	ny State requiremen	its.*	Benson Que		
See also space 17 below.) Well At surface	is located 1050	' FNL & 23	STO.	Gravburg N	onth_	
FEL of Section 34,	T-18-S. R-30-E.	. Unit Let	ter 'd'.	11. SEC., T., R., M., OR B. SURVEY OR AREA	LE. AND	
Eddy, County, New M		, •	4	Sec. 34,		
naay, country, new m	CAICO.			T-18-S, R-3	O-F	
14. PERMIT NO.	15. ELEVATIONS (Show whether	DF, RT, GR, etc.)	· · · · · · · · · · · · · · · · · · ·	12. COUNTY OR PARISH		
	olina e	()		Eddy	New Mexic	0
Regular	3451	•			<u> </u>	
16. Check Ap	propriate Box To Indicate	Nature of Notice	ce, Report, or C	Other Data		
NOTICE OF INTEN	TION TO:	1	SUBSEQU	ENT REPORT OF:		
	and the classes	WATER SI	HUT-OFF	REPAIRING W	VELL	
	PULL OR ALTER CASING	1	TREATMENT	ALTERING CA	SING	
7.	MULTIPLE COMPLETE		(ABANDONMEN		
SHOOT OR ACIDIZE X	ABANDON*		OR ACIDIZING		-	
REPAIR WELL	CHANGE PLANS	(Other)	TE . Report results	of multiple completion	on Well	
(Other)		Con	apletion or Recompl	letion Report and Log for	'm.)	
 DESCRIBE PROPOSED OR COMPLETED OPE proposed work. If well is directio nent to this work.) * 	RATIONS (Clearly state all pertin mally drilled, give subsurface lo	nent details, and gi neations and measur	ve pertinent dates, ed and true vertica	including estimated date al depths for all markers	of starting any and zones perti-	

- 1. Rig up. Pull rods & pump. Install BOP. Pull Tubing.
- 2. Set packer. Spot acid over perforations 2830'-3077'.
- Acidize perforations w/2000 gal. 15% NE Acid. Swab Well. 3.
- 4. Treat w/55 gal. Scale inhibitor mixed w/275 gal. treated fresh water.
- 5. Flush w/50 Bbl. Treated fresh water.
- 6. Run pumping equipment. Test & return to production.

RECEIVED

JUL 1 9 1976

U.S. GEOLOGICAL SURVEY. ARTESIA, NEW MEXICO

18. I hereby certify that the foregoing is true and correct	TITLE Asst. Dist. Supt.	DATE 7-15-76
(This space for Federal or State office use) APPROVED BY CONDITIONS OF APPROVAL, IF ANY:	TITLE	DATE
JUL: 20 1976		

*See Instructions on Reverse Side