

N. M. O. C. C. COPY
UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPI
(Other instructions
verse side)FE-
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 029395 (b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Turner "B" A

9. WELL NO.

60

10. FIELD AND POOL, OR WILDCAT

Grayburg Jackson OGSA

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

29-T17S-R31E

12. COUNTY OR PARISH

Eddy

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

RECEIVED

2. NAME OF OPERATOR

Atlantic Richfield Company

JAN 20 1975

3. ADDRESS OF OPERATOR

P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

ARTESIA, OFFICE

1980' FSL & 1980' FWL (Unit letter K)

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

3736' GR

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☒
☒
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

REPAIRING WELL

☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3626', PBD 3624'. Presently completed from perfs 3470-3488' & 3513-24'.

Propose to add perforations in same formation and treat all perfs in the following manner:

1. Install BOP & POH w/completion assy.
2. GIH w/2-7/8" tbg & pkr. Set pkr @ 3455'. Treat perfs 3470-3488' & 3513-24' w/10,000 gals gelled water & 10,000# 20/40 sd followed by ARCO scale inhibitor.
3. POH w/2-7/8" tbg.
4. Perforate 3273-75, 3350, 3412-15' w/1 JSPF = 8 holes.
5. GIH w/2-7/8" tbg, RBP & pkr. Set RBP @ 3450' & pkr @ 3200'.
6. Treat perfs 3273-3415' w/30,000# 20/40 sd & 30,000 gals gelled water w/ARCO scale inhibitor. Use diverting agent to treat in 3 stages.
7. POH w/pkr & RBP. CO to PBD 3624'. Run production completion assy & return to production.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Drlg. Supv.

DATE 1/14/75

(This space for Federal or State office use)


APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



ATLANTIC RICHFIELD COMPANY
Blow Out Preventer Program

Lease Name Turner "B" A

Well No. 60

Location Sec 29, T17S, R31E
Eddy County, N.M.

BOP to be tested before installed on well and will be maintained in good working condition during workover. All wellhead fittings to be of sufficient pressure to operate in a safe manner.

RECEIVED

JAN 16 1975

U. S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO