

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION

MAR 1 1973

O. C. C.
ARTESIA, OFFICEForm C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.
E-7873**SUNDRY NOTICES AND REPORTS ON WELLS**(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	7. Unit Agreement Name South Hope Unit
2. Name of Operator SUN OIL COMPANY	8. Farm or Lease Name
3. Address of Operator P. O. BOX 1831, MIDLAND, TEXAS 79701	9. Well No. 1
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 1845.69 FEET FROM THE West LINE, SECTION 30 TOWNSHIP 18-S RANGE 23-E NMPM.	10. Field and Pool, or Wildcat, South Hope Strawn Gas
15. Elevation (Show whether DF, RT, GR, etc.) GR. 4059	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Load hole w/9.5# mud. Install BOP, unseat pkr & circ. mud.
2. Spot 50 sx cmt., reseal pkr & sqz. 25 sx to formation (7326-7336) & spot remaining cmt. above & below Mod.-D-Pkr. POOH
3. Locate free point, cut 7" csg. & pull. *TOC @ 5675 by Temp Survey*
4. Spot 100' plug 50' in & out top of 7" csg.
5. Plug w/40 sx across Abo @ 3360-3346'. *3440*
6. Spot 40 sx plug across bottom of 9-5/8" @ 1750-1850' & 40 sx plug 550-650'.
7. Place 10' cmt plug @ surface & weld on steel marker plate.
8. Clean location - PSA Final.

Note: Anticipated plugging date is 5-1-73.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Charles Gray TITLE **Proration Clerk** DATE **2-28-73**APPROVED BY W. A. Gussert TITLE **OIL AND GAS INSPECTOR** DATE **MAR 2 1973**CONDITIONS OF APPROVAL, IF ANY: **Notify N.M.O.C.C. in sufficient time to witness***Plugging*