## COPY

SUBMIT IN TRIPLICAT DEPARTMENT OF THE INTERIOR (Other instructions on verse side)

GEOLOGICAL SURVEY

Form approved

Budget Port Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM-033775

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS
--------	---------	-----	---------	----	-------

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

1.		RECEIVE7. DATE AGREEMENT NAME					
	OIL GAS OTHER	Water Injection	Well	North Bens	<u>Son Queen</u> Unit		
2.	NAME OF OPERATOR		MAY 2 0 197	8. FARM OR LEASE NA	ME - SOLO DIE GELEG		
	TEXACO Inc. V		IVIAI & U IST	North Ber	nson Queen Uni		
3.	ADDRESS OF OPERATOR			9. WELL NO.			
	P.O. Box 728, Hob	bs, New Mexico 8	88240 <b>D. C. C.</b>	16			
4.	LOCATION OF WELL (Report location cle See also space 17 below.) At surface	arly and in accordance with any S	tate requirements.	North Ber Grayburg	nson Queen		
	1650 FSL & 1651 F	EL of Section 28,	T-18-S,	11. SEC., T., R., M., OR SURVEY OR AREA			
	R-30-E, Unit Letter "J", Eddy Co., Ne		lew Mexico	Sec. 28, 7	r-18-s, R-30-E		
14.	PERMIT NO.	15. ELEVATIONS (Show whether DF, I	RT, GR, etc.)	12. COUNTY OR PARISE	H 13. STATE		
	Regular	3499' DE	1	Eddy	New Mexico		
16.	Check App	propriate Box To Indicate No	iture of Notice, Report, or C	Other Data			
	NOTICE OF INTENT	ion to:	SUBSEQUENT REPORT OF:				
		TLL OR ALTER CASING	WATER SHUT-OFF	REPAIRING ALTERING O			
		BANDON*	SHOOTING OR ACIDIZING	ABANDONME	ENT*		
	REPAIR WELL, CI	HANGE PLANS X	(Other)				
	(Other) Addl. Perforat	ions in same Zone	(Note: Report results Completion or Recomp	of multiple completion letion Report and Log fo	on Well		
17.	proposed work. If well is direction nent to this work.) *	ATIONS (Clearly state all pertinent ally drilled, give subsurface locations)	details, and give pertinent dates, one and measured and true vertic	, including estimated da al depths for all marker	te of starting any rs and zones perti-		

- Install BOP. Pull injection tubing & packer. 1. Rig up.
- 2. Set RBP @ 3050'.

18.

- Perforate 45" OD Casing w/2 JSPF from 3006'-3014'. Set packer @ 2980'.
- Acidize perforations 3006'-3014' w/500 gal. Mud Acid w/clay stabilizers. Run injection tubing & packer. Test & return to injection.

RECEIVED

MAY 1 8 1976

U. S. GEOLOGICAL SURVEY ARTESIA, NEW MEXICO

I hereby certify that the foregoing is true and correct				
SIGNED JACKET	TITLE:	Asst. Dist. Supt.	DATE	May 17, 1976
(This space for Federal or State office use)				
APPROVED BY	TITLE		DATE	
CONDITIONS OF APPROVAL, IF ANY:				
APPROVED				
*Se	e Instruc	tions on Reverse Side		