	BUREAU UT LAND		(Other instance on	S. LEASE DESIGNATION AND SERIAL NO. NM 033775
SUNDRY	NOTICES AND	REPORTS	N WELLS	G. IF INDIAN, ALLOTTEE OR TRIBE NAME
(Do not use this form fo Use "A	r proposals to drill or APPLICATION FOR PE	to deepen or plug bac RMIT-" for such prop	k to a different reservoir.	C/SF
	Water	- T		7. UNIT AGREEMENT NAME
NAME OF OPERATOR	water	Injection	<u>Well</u>	North Benson Queen Uni
Texaco Inc.			RECEIVED	8. PARK OR LEASE NAME
. ADDRESS OF OPERATOR			007.004000	9. WBLL NO.
P. O. BOX 728, LOCATION OF WELL (Report low See also space 17 below.)	Hobbs, New	Mexico 88	<u>40</u> OCT 20 1986	9
See also space 17 below.) At surface		cordance with any S	o, C. D.	10. FIELD AND POOL, OR WILDCAT
Unit Letter "F"	', 1980' FNL	& 1980' FV	T. ARTESIA, OFFICE	Benson Queen Grayburg, 1 11. SRC. T. B. M., OB BLK. AND NURVEY OF AREA
4. PERMIT NO.	15. BLEVATION	a (Show whether DF, M	(CE. etc.)	<u>/</u> <u>Sec. 28, т-17-S, R-30-Е</u>
		3436' GR	-	12. COUNTY OR PARISE 18. STATE
. Che	ck Appropriate Ro		ure of Notice, Report, or	Eddy N.M.
NOTICE OF	T INTENTION TO :	· · · · · · · · · · · · · · · ·		
TEST WATER SHUT-OFF	PULL OR ALTER (r	QUENT REPORT OF :
FRACTURE TREAT	MULTIPLE COMPI		WATER SHUT-OFF Fracture treatment	REPAIRING WELL
SHOOT OR ACIDIZE	ABANDON*		SHOOTING OR ACIDIZING	ALTERING CASING
(Other) Temporar	CHANGE PLANS		(Other)	
	y Abandon		Completion or Record	ts of multiple completion on Well spletion Report and Log form.) a, including estimated date of starting any ical depths for all markers and gones perti-
2. MIRIL Dilli			(Held for reme	dial work).
 MIRU Pulling Release pach Set CIBP @ 2 inhibited wat Rig down Pull 	g Unit. Ins ker. POH wi 2600'. Dump ater. Test lling Unit. MONTH PERIOD	stall BOP. th tubing a b 10' of cen	and packer. Ment on top of (dial work). CIBP. Load hole with
 MIRU Pulling Release pach Set CIBP @ 2 inhibited wat Rig down Pull APPROVED FOR 12 M ENDING 10-16 	g Unit. Ins ker. POH wi 2600'. Dump ater. Test lling Unit. MONTH PERIOD 5-87	tall BOP. th tubing a 0 10' of cen casing to 5	and packer. Ment on top of (
 MIRU Pulling Release pach Set CIBP @ 2 inhibited wat Rig down Pull Rig down Pull Rig down Pull Rig down Pull I hereby certify that the forego SIGNED	g Unit. Ins ker. POH wi 2600'. Dump ater. Test lling Unit. MONTH PERIOD 5-87	W. B	and packer. Ment on top of (
 APPROVED FOR 12 // Control of the space for Fadesal or State APPROVED FOR 12 // Control of the space for Fadesal or State 	g Unit. Ins ker. POH wi 2600'. Dump ater. Test lling Unit. MONTH PERIOD 5-87	W. B	and packer. Ment on top of (500 PSI.	CIBP. Load hole with
 MIRU Pulling Release pach Set CIBP @ 2 inhibited wat Rig down Pulling 	g Unit. Ins ker. POH wi 2600'. Dump ater. Test lling Unit. MONTH PERIOD 5- 87	W. B	and packer. Ment on top of (500 PSI.	CIBP. Load hole with

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.