NUMBER OF COPI	ES RECEI	VED	1	_
ild.	STRIBUTI	ON .	3	
SANTA FE	17	T	 _	
FILE		1		
U.S.G.S.				 _
LAND OFFICE		†		_
	OIL	1		_
TRANSPORTER	GAS	1		
PRORATION OFFICE				_
OPERATOR		1		

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico

MISCELLANEOUS NOTICES

strict Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

			-	ing Below
OTICE OF IN O CHANGE P			Notice of Intention to Temporarily Abandon Well	Notice of Intention to Drill Deeper
OTICE OF IN		x	Notice of Intention to Plug Back	Notice of Intention to Set Liner
Notice of In to Squeeze	TENTION		Notice of Intention to Acdize	Notice of Intention to Shoot (Nitro)
Notice of In O Gun Perf			Notice of Intention (Other)	Notice of Intention (Other)
	RVATION CO		Hobbs, New Mexico	3-2-6l4 (Date)
Gentlemen:			(Field)	(Date)
New Me	rico Stat	e #AR#		
YW	SE (C	ompany or Operator)	Jean Lease	Well No
	Subdivision)	of Sec	, T. 100 R. 23E N	MPM., South Hope Strawn
w/mud.	Lay plu	gs as follow	s 50 sx from 4350-4550.	n bottom 7618-7218. Load hole 50 ax from 1511-1336, 50 ax from
w/mud. 567-39	2, 10 sx	gs as follow in top of 8	s 50 sx from 4350-4550, 5 5/8= csg.	50 ax from 1511-1336, 50 ax from
w/mud. 567-39 Propose	2, 10 sx	gs as follow in top of 8	s 50 sx from 4350-4550, 5 5/8= csg.	50 ax from 1511-1336, 50 ax from
w/mud. 567-39 Propose	Lay plu 2, 10 sx : e to insta	gs as follow in top of 8	s 50 sx from 4350-4550, 5 5/8= csg.	50 ax from 1511-1336, 50 ax from
w/mud. 567-39 Propose	Lay plu 2, 10 sx : e to insta	gs as follow in top of 8	s 50 sx from 4350-4550, 5 5/8= csg.	50 ax from 1511-1336, 50 ax from
w/mud. 567-39 Propose	Lay plu 2, 10 sx : e to insta	gs as follow in top of 8	s 50 sx from 4350-4550, 5 5/8= csg.	levelled the location and clean RECEIVED
w/mud. 567-39 Propose	Lay plu 2, 10 sx : e to insta	gs as follow in top of 8	s 50 sx from 4350-4550, 5 5/8= csg.	levelled the location and clean RECEIVED
w/mud. 567-39 Propose	Lay plu 2, 10 sx : e to insta	gs as follow in top of 8	s 50 sx from 4350-4550, 5 5/8= csg.	50 ax from 1511-1336, 50 ax from
w/mud. 567-39 Propose it of	Lay plug 2, 10 sx : e to insta all junk.	gs as follow in top of 8 all dry hole	s 50 sx from 4350-4550, 5 5/8= csg.	levelled the location and clean RECEIVED
w/mud. 567-39 Propose it of	Lay plug 2, 10 sx : e to insta all junk.	gs as follow in top of 8 all dry hole	s 50 sx from 4350-4550, 15/8" csg. marker. Fill all pits, 1	levelled the location and clean RECEIVED MAR 3 1964 MAR 3 C. C
W/mud. 567-39 Propose 1t of Approved	Lay plug 2, 10 sx : e to insta all junk.	gs as follow in top of 8 all dry hole	s 50 sx from 4350-4550, 15/8 csg. marker. Fill all pits, 1	Sunray DX 011 Company
W/mud. 567-39 Propose 1t of Approved Except as foll	Lay plug 2, 10 sx : e to insta all junk.	gs as follow in top of 8 all dry hole	s 50 sx from 4350-4550, 15/8 csg. marker. Fill all pits, 1	Sunray DX 011 Company Company or Operator V. R. Mayabb
W/mud. 567-39 Propose 1t of Approved Except as foll	MAR 3	gs as follow in top of 8 all dry hole	s 50 sx from 4350-4550, 5/8 csg. marker. Fill all pits, 1	Sunray DX Oil Company Company or Operator V. R. Mayabb Latrict Engineer
Approved	MAR 3	gs as follow in top of 8 all dry hole 1964	s 50 sx from 4350-4550, 5/8 csg. marker. Fill all pits, 1	Sunray DX Oil Company Company or Operator Send Communications regarding well to: