Form 9-331	NITED STATES			Form approved.	
(May 1963)	EPARTMENT OF THE I			Budget Bureau N DESIGNATION AND	
	GEOLOGICAL SURV	, ,		3375 NMD3.	
SUNDR	Y NOTICES AND REPC			DIAN, ALLOTTEE OR	
(Do not use this form Use	for proposals to drill or to deepen "APPLICATION FOR PERMIT" for	or plug back to a different reservoir. or such proposals.)	NONE		
1. OIL X GAS WELL				AGREEMENT NAME	
WELL WELL 2. NAME OF OPERATOR	OTHER		NONE	OR LEASE NAME	7.
3. ADDRESS OF OPERATOR	TEXACO Inc. 4		L.R	. Manning '	'B'' N
		8 - Hobbs, New Mexico	9. WELL 19	NO.	
4. LOCATION OF WELL (Report See also space 17 below.) At surface	t location clearly and in accordance v	vith any State requirements.*		AND POOL, OR WI	
	01 from the West Line	, and 990' from the No.	rth 11 arc	h Bénson Qu	
Line of Section	27, T-18-S, R-30-E,	Eddy County, New Mexic		T., R., M., OR BLK. RVEY OR AREA	AND
		<i>y</i>		27, T-18-3	5, R-
14. PERMIT NO.	15. ELEVATIONS (Show w	N		TY OR PARISH 13	
Regular			Eddy	<u>-</u>	N. M
16. C	heck Appropriate Box To Ind	icate Nature of Notice, Report,	or Other Date	a	
	E OF INTENTION TO:		BSEQUENT REPORT		
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF		REPAIRING WELL	
FRACTURE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT		ALTERING CASING	,
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZIN	x	ABANDONMENT*	
REPAIR WELL	CHANGE PLANS	(Other)		e completion on V	
(Other) 17. DESCRIBE PROPOSED OR COMP proposed work. If well nent to this work.) *	is encountary armou, give subsuit	Description of Receiver of the second	dates, including e vertical depths fo	estimated date of or all markers and	startin, l zones
17. DESCRIBE PROPOSED OR COMP proposed work. If well	The following work	Dertinent details, and give pertinent acce locations and measured and true	dates, including e vertical depths fo subject we	estimated date of or all markers and ell:	startinj I zones
17. DESCRIBE PROPOSED OR COMP proposed work. If well	The following work	L Completion or Repertinent details, and give pertinent accelocations and measured and true to has been completed on equipment, and clean or	dates, including e vertical depths fo subject we	estimated date of or all markers and ell:	starting l zones
17. DESCRIBE PROPOSED OR COMP proposed work. If well	The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2	L Completion or Re pertinent details, and give pertinent acce locations and measured and true has been completed on equipment, and clean or 2" O. D. Casing with to	tates, including evertical depths for subject we it to a tot vo jet shot	estimated date of or all markers and tal ts @	starting I zones
17. DESCRIBE PROPOSED OR COM proposed work. If well nent to this work.) *	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 1 	L Completion or Repertment details, and give pertinent acce locations and measured and true with the set locations and measured and true with the set locations and measured and true with the set location of	tates, including evertical depths for subject we it to a tot vo jet shot	estimated date of or all markers and tal ts @	starting l zones
17. DESCRIBE PROPOSED OR COM proposed work. If well nent to this work.)*	The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2	L Completion or Re pertinent details, and give pertinent acce locations and measured and true has been completed on equipment, and clean or 2" O. D. Casing with to	tates, including evertical depths for subject we it to a tot vo jet shot	estimated date of or all markers and tal ts @	starting I zones
 DESCRIBE TROPOSED OR COMPOPOSEd work. If well nent to this work.)* E C E I V E D JUN 3 0 1967 	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 	L Completion or Repertinent details, and give pertinent accelocations and measured and true with the second sequipment, and clean or sequipment, and sequepment, and clean or sequepment, and clean	subject we to a tot vo jet shot	estimated date of or all markers and tal ts @ ', &	starting l zones
17. DESCRIBE TROPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UUN 3 0 1967 C. C. C.	 The following work 1. Pull the pump of depth of 3400' 2. Perforate 4 1/2 2850', 2917', 23240'. 3. Frac perforation & 112,500 pound 	L Completion or Re pertinent details, and give pertinent acce locations and measured and true has been completed on equipment, and clean or 2" O. D. Casing with to	subject we to a tot so jet shot 160', 3200'	estimated date of or all markers and tal ts @ ', & ter	startinj i zones
 DESCRIBE TROPOSED OR COMPOPOSEd work. If well nent to this work.)* E C E I V E D JUN 3 0 1967 	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 	L Completion or Repertinent details, and give pertinent acce locations and measured and true with the second secon	subject we subject we to jet shot 160', 3200' s fresh wat	estimated date of or all markers and tal ts @ ', & ter d,	
17. DESCRIBE TROPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UUN 3 0 1967 C. C. C.	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 	L Completion or Repertinent details, and give pertinent acce locations and measured and true with the second secon	subject we subject we to jet shot 160', 3200' s fresh wat	estimated date of or all markers and tal ts @ ', & ter d,	
17. DESCRIBE TROPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UUN 3 0 1967 C. C. C.	 The following work 1. Pull the pump depth of 3400' 2. Perforate h 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well 	L Completion or Repertinent details, and give pertinent acce locations and measured and true with the second secon	subject we subject we to jet shot 60', 3200 s fresh wat ecover load	estimated date of or all markers and tal ts @ ', & ter d,	
17. DESCRIBE TROPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UUN 3 0 1967 C. C. C.	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 	L Completion or Repertinent details, and give pertinent accelocations and measured and true with the second	subject we subject we to jet shot 60', 3200 s fresh wat ecover load	estimated date of or all markers and tal ts @ ', & ter d,	
17. DESCRIBE TROPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UUN 3 0 1967 C. C. C.	 The following work 1. Pull the pump depth of 3400' 2. Perforate h 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well 	L Completion or Repertinent details, and give pertinent acce locations and measured and true with the second secon	subject we subject we to a tot to a tot o jet shot 60', 3200 s fresh wat ecover load	estimated date of or all markers and ell: tal ts @ ', & ter d, ENED	
17. DESCRIBE TROPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UUN 3 0 1967 C. C. C.	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 	L Completion or Repertinent details, and give pertinent acce locations and measured and true with the second secon	subject we subject we to a tot to a tot o jet shot 60', 3200 s fresh wat ecover load	estimated date of or all markers and ell: tal ts @ ', & ter d, ENED	
17. DESCRIBE TEOPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UN 3 0 1967 C. C. C. ARTESIA, OFFICE	 The following work Pull the pump depth of 3400' Perforate 4 1/2 2850', 2917', 3240'. Frac perforation & 112,500 pound and test. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	L Completion or Repertinent details, and give pertinent acce locations and measured and true with the second secon	subject we subject we to a tot to a tot o jet shot 60', 3200 s fresh wat ecover load	estimated date of or all markers and ell: tal ts @ ', & ter d, ENED	
 17. DESCRIBE PROPOSED OR COMProposed work. If well nent to this work.)* E C E I V E D JUN 3 0 1967 O. C. G. ARTESIA, OFFICE 18. I hereby certify that the for 1/5 111 	 The following work 1. Pull the pump depth of 3400¹ 2. Perforate 4 1/2 2850¹, 2917¹, 3240¹. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	L Completion or Repertment details, and give pertinent accelocations and measured and true we have been completed on equipment, and clean or ' 2" O. D. Casing with the 3070', 3120', 3130', 31 ons with 75,000 gallon: ds sand. Swab well, rependent of the second s	subject we rertical depths fo subject we it to a tot to jet shot 160', 3200' s fresh wat ecover load 0 P. M. Jur SW.	estimated date of or all markers and ell: tal ts @ ', & ter d, EIVED N291967 N291967 States St States MEN. MEN	
17. DESCRIBE TROPOSED OR COM proposed work. If well nent to this work.)* E C E I V E D UN 3 0 1967 C. C. C. ARTESIA, OFFICE	 The following work 1. Pull the pump depth of 3400¹ 2. Perforate 4 1/2 2850¹, 2917¹, 3240¹. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	L Completion or Repertinent details, and give pertinent acce locations and measured and true with the second secon	subject we rertical depths fo subject we it to a tot to jet shot 160', 3200' s fresh wat ecover load 0 P. M. Jur SW.	estimated date of or all markers and ell: tal ts @ ', & ter d, ENED	
 17. DESCRIBE TROPOSED OR COMProposed work. If well nent to this work.)* E C E I V E D JUN 3 0 1967 D. C. C. ARTESIA, OFFICE 18. I hereby certify that the formation of the signed with the signed wit	 The following work 1. Pull the pump of depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	L Completion or Repertment details, and give pertinent accelocations and measured and true we have been completed on equipment, and clean or ' 2" O. D. Casing with the 3070', 3120', 3130', 31 ons with 75,000 gallon: ds sand. Swab well, rependent of the second s	subject we rertical depths fo subject we it to a tot to jet shot 160', 3200' s fresh wat ecover load 0 P. M. Jur SW.	estimated date of or all markers and ell: tal ts @ ', & ter d, EIVED N291967 N291967 States St States MEN. MEN	
 17. DESCRIBE TROPOSED OR COMProposed work. If well nent to this work.)* E C E I V E D JUN 3 0 1967 D. C. G. ARTESIA, OFFICE 18. I hereby certify that the fraction of the supervised of	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	<u>Completion or Repertinent details, and give pertinent accelocations and measured and true was been completed on equipment, and clean or equipment, and clean or '''''''''''''''''''''''''''''''''''</u>	subject we rertical depths fo subject we it to a tot to jet shot 160', 3200' s fresh wat ecover load 0 P. M. Jur SW.	estimated date of or all markers and ell: tal ts @ ', & ter d, N291967 N291967 N291967 State Sta	
 17. DESCRIBE TROPOSED OR COMPROVED BY	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	<u>Completion or Repertinent details, and give pertinent accelocations and measured and true was been completed on equipment, and clean or equipment, and clean or '''''''''''''''''''''''''''''''''''</u>	subject we rertical depths fo subject we it to a tot vo jet shot 160', 3200 s fresh wat ecover load 0 P. M. Jur BW. U.S. U.S. U.S. U.S.	estimated date of or all markers and ell: tal ts @ ', & ter d, N291967 N291967 N291967 State Sta	
 17. DESCRIBE TROPOSED OR COMPROPOSEd work. If well nent to this work.)* E C E I V E D IUN 3 0 1967 I. C. C. ARTESIA, OFFICE 18. I hereby certify that the fraction of the successful of	 The following work 1. Pull the pump depth of 3400' 2. Perforate 4 1/2 2850', 2917', 3240'. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	<u>Completion or Repertinent details, and give pertinent accelocations and measured and true was been completed on equipment, and clean or equipment, and clean or '''''''''''''''''''''''''''''''''''</u>	subject we rertical depths fo subject we it to a tot vo jet shot 160', 3200 s fresh wat ecover load 0 P. M. Jur BW. U.S. U.S. U.S. U.S.	estimated date of or all markers and ell: tal ts @ ', & ter d, N291967 N291967 N291967 State Sta	
 17. DESCRIBE TROPOSED OR COMProposed work. If well nent to this work.)* E C E I V E D JUN 3 0 1967 D. C. G. ARTESIA, OFFICE 18. I hereby certify that the fraction of the supervised of	 The following work 1. Pull the pump of depth of 3400¹ 2. Perforate 4 1/2 2850¹, 2917¹, 3240¹. 3. Frac perforation & 112,500 pound and test. 4. On 24 Hour Pote 26, 1967, well GOR - 1420 GRAVITY - 32.6 	<u>Completion or Repertinent details, and give pertinent accelocations and measured and true was been completed on equipment, and clean or equipment, and clean or '''''''''''''''''''''''''''''''''''</u>	subject we rertical depths fo subject we it to a tot vo jet shot 160', 3200 s fresh wat ecover load 0 P. M. Jur BW. U.S. U.S. U.S. U.S.	estimated date of or all markers and ell: tal ts @ ', & ter d, N291967 N291967 N291967 State Sta	