

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
RECEIVED BY
SANTA FE, NEW MEXICO 87501
MAR - 2 1987
O. C. D.
ARTESIA, OFFICE

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Martin
3. Address of Operator 105 So. 4th St., Artesia, NM 88210	9. Well No. 4
4. Location of Well UNIT LETTER <u>B0</u> , <u>500</u> FEET FROM THE <u>South</u> LINE AND <u>2070</u> FEET FROM THE <u>East</u> LINE, SECTION <u>15</u> TOWNSHIP <u>18S</u> RANGE <u>26E</u> NMPM.	10. Field and Pool, or Wildcat Atoka San Andres
15. Elevation (Show whether DF, RT, GR, etc.) <u>3336' 6"</u>	12. County Eddy

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well has 5½" casing at 2221' w/cement to surface, 8-5/8" casing at 1144' w/cement to surface.
Propose to plug well as follows:
Spot two 50 sx plugs over perfs at 1490-2210', ^{Tag} displace w/heavy mud.
Spot ~~10~~ 25 sx plug across 8-5/8" shoe
Spot 10 sx plug at surface.
Set dry hole marker.
Clean location.

Plugging

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Juanita Doodley</u>	TITLE <u>Production Supervisor</u>	DATE <u>2-27-87</u>
APPROVED BY <u>Mike Williams</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>MAR 04 1987</u>

CONDITIONS OF APPROVAL, IF ANY: