

5F/file

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Artesia, NM 89210  
RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☒ P&A ARTESIA, OFFICE

2. NAME OF OPERATOR ARCO Oil and Gas Company  
Division of Atlantic Richfield Company

3. ADDRESS OF OPERATOR  
P. O. Box 1710, Hobbs, New Mexico 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980' FNL & 660' FWL  
AT TOP PROD. INTERVAL: as above  
AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input checked="" type="checkbox"/>		<input type="checkbox"/>
(other)			

5. LEASE  
LC-060122

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME  
Trigg Federal

9. WELL NO.  
1

10. FIELD OR WILDCAT NAME  
~~Atoka East Morrow Gas~~

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
27-18S-27E

12. COUNTY OR PARISH Eddy 13. STATE New Mexico

14. API NO.


15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3425' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Propose to P&A in the following manner:

1. Rig up. RIH w/2-7/8" tbg OE and tag cmt plug @ 1420'. Fill hole w/mud, pull tbg to 550' & spot Cl C Neat cmt 550' to surf.
2. Remove wellhead, cut off csg 4' below GL.
3. Weld cap on top of csg. Install regulation dry hole marker. Clean and level location for abandonment.



Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Elizabeth A. Bush TITLE Drig. Engr. DATE 6/24/82

APPROVED (This space for Federal or State office use)  
(Orig. Sgd.) PETER W. CHESTER TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

JUN 29 1982  
FOR  
JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side