

NO. OF COPIES RECEIVED	2
DISTRIBUTION	
ANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

RECEIVED

NEW MEXICO OIL CONSERVATION COMMISSION
MAY 1 1975

O. C. C.
ARTESIA, OFFICE

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-9262	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Injection		7. Unit Agreement Name North Benson Queen Unit
2. Name of Operator TEXACO Inc.		8. Farm or Lease Name
3. Address of Operator P. O. Box 728, Hobbs, New Mexico 88240		9. Well No. 42
4. Location of Well UNIT LETTER F , 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 32 TOWNSHIP 18-S RANGE 30-E NMPM.		10. Field and Pool, or Wildcat North Benson Queen Grayburg
15. Elevation (Show whether DF, RT, GR, etc.) 3415 DF		12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER Acidize <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Rig up pulling unit, and pull 2 3/8" tubing and packer
2. Run RBP & packer. Set RBP at 3150' and packer at 3070'. Treat perforations 3095' and 3124' w/ regular 15% acid w/ 10% by volume Halliburton's Musol and w/5 gals. per 1500 gals. Morflo. Displace acid w/ fresh water shut well in 30 min. Swab acid residue. Test injectivity of interval w/ fresh water at injection pressure 1600 psi.
3. Move RBP to 3020 & packer to 2950'. Treat perfs 2955' to 2995 w/ 1000 gals. acid same as Step #2.
4. Pull RBP and packer.
5. Run injection tubing and packer. Load annulus w/ inhibited fluid and return well to injection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE **Asst. Dist. Supt.** DATE **April 29, 1975**

APPROVED BY [Signature] TITLE **SUPERVISOR, DISTRICT II** DATE **MAY 1 1975**

CONDITIONS OF APPROVAL, IF ANY: