Form 194330 TT COME LONG DEC. 1973	Form Approved.
Draws Augusted States NOV 13 1984	Budget Bureau No. 42-R1424
DEPARTMENT OF THE INTERIOR	5. LEASE LC - 028772 a
	6. FINDIAN, ALLOTTEE OR TRIBE NAME
GEOLOGICAL SURVEY ARTESIA, OFFICE	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	Ballard Grayburg San Andres Uni
	8. FARM OR LEASE NAME Tract No. 1
1. oil gas well other X-Water Injection Well	9. WELL NO.
2. NAME OF OPERATOR	6
Anadarko Production Company	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P. O. Drawer 130, Artesia, New Mexico 88210	Loco Hills-Queen-Grayburg-San A 11. SEC., T., R., M., OR BLK. AND SURVEY OR
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	AREA
below.) 900 FINIT & 330 FINIT	7 - 185 - 29E
AT SURFACE: 770 FRE & 550 FRE AT TOP PROD. INTERVAL: Same	12. COUNTY OR PARISH 13. STATE
AT TOTAL DEPTH: Same	Eddy New Mexico 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	3630 GL
TEST WATER SHUT OFF	
FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9–330.)
(other)	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is di measured and true vertical depths for all markers and zones pertinent	rectionally drilled, give subsurface locations and t to this work.)*
1. Rig up pulling unit; TOH with packer and tubi	ng.
2. GIH with packer and RBP.	
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin.</li> </ol>	
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> </ol>	
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu</li> </ol>	g injection water and break bing; circulate hole with fresh
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casi</li> </ol>	g injection water and break bing; circulate hole with fresh
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> </ol>	g injection water and break bing; circulate hole with fresh
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casi:</li> </ol>	g injection water and break bing; circulate hole with fresh
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> </ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> </ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected.
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> <li><u>Note</u>: Will run injection profile after sufficient</li> </ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected.
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> <li><u>Note</u>: Will run injection profile after sufficient.</li> <li>Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. Set @Ft.
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> <li><u>Note:</u> Will run injection profile after suffice</li> <li>Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> <li><u>Note</u>: Will run injection profile after sufficient Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> <li>Note: Will run injection profile after sufficient Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> <li><u>Note</u>: Will run injection profile after sufficient Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 
<ol> <li>GIH with packer and RBP.</li> <li>Isolate all existing Grayburg perfs not takin down with acid.</li> <li>TOH with packer and RBP.</li> <li>GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>Return well to injection.</li> <li>Note: Will run injection profile after suffice</li> <li>Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 
<ol> <li>2. GIH with packer and RBP.</li> <li>3. Isolate all existing Grayburg perfs not takin down with acid.</li> <li>4. TOH with packer and RBP.</li> <li>5. GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>6. Return well to injection.</li> <li><u>Note</u>: Will run injection profile after sufficient</li> <li>Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 
<ol> <li>2. GIH with packer and RBP.</li> <li>3. Isolate all existing Grayburg perfs not takin down with acid.</li> <li>4. TOH with packer and RBP.</li> <li>5. GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>6. Return well to injection.</li> <li><u>Note:</u> Will run injection profile after sufficient Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 
<ol> <li>2. GIH with packer and RBP.</li> <li>3. Isolate all existing Grayburg perfs not takin down with acid.</li> <li>4. TOH with packer and RBP.</li> <li>5. GIH with injection packer on plastic lined tu water and chemical; set packer and test casin NMOCD rules and regulations.</li> <li>6. Return well to injection.</li> <li><u>Note</u>: Will run injection profile after sufficient</li> <li>Subsurface Safety Valve: Manu. and Type</li></ol>	g injection water and break bing; circulate hole with fresh ng to 500# in accordance with cient water has been injected. 