

C/S 74

Form 9-331
Dec. 1973

O+5 - USGS - P.O. Box 1857
Roswell, NM 88201

1 - Engr. LM
1 - Foreman EF

1 - File
Form Approved. 1-Laura Rich.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☒ gas well ☐ other ☐

2. NAME OF OPERATOR
Getty Oil Company ✓

3. ADDRESS OF OPERATOR
P.O. Box 730 Hobbs, NM 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: Ltr. F, 1980' FNL & 1980' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input checked="" type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other)			

5. LEASE
LC-029418(b)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME RECEIVED

8. FARM OR LEASE NAME
Iea "D" MAR 14 1983

9. WELL NO.
7 O. C. D.

10. FIELD OR WILDCAT NAME ARTESIA OFFICE
Grayburg Jackson

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 26, T17S, R31E

12. COUNTY OR PARISH Eddy 13. STATE NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3549 DF
3850

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Pull rods, pump, and tubing.
2. Run 4 3/4" bit and casing scraper to 3971' PBTD.
3. Set packer at + 3740'.
4. Acidize perms 3772-3960 with 1500 gal. 15% Hcl.
5. TOH w/packer.
6. Set RBP at + 3740', set packer at 3300'.
7. Acidize perms 3372'-3728' with 1500 gal. 15% Hcl.
8. TOH w/RBP and packer.
9. Return to production.

RECEIVED

MAR 9 1983

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.
OIL & GAS

18. I hereby certify that the foregoing is true and correct

MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO

SIGNED

DATE _____ TITLE Area Superintendent

DATE

APPROVED

(This space for Federal or State office use)

(Orig. Sgn.) PETER W. CHESTER
APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

MAR 11 1983

FOR

JAMES A. GILLHAM
DISTRICT SUPERVISOR

*See instructions on Reverse Side