

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

RECEIVED

MAR 15 1978

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-707

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REOPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)	
1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/> ARTESIA, OFFICE	7. Unit Agreement Name
2. Name of Operator ESTORIL PRODUCING CORPORATION	8. Farm or Lease Name Maralo State Com.
3. Address of Operator 1120 VAUGHN BLDG. MIDLAND, TEXAS	9. Well No. 1 One
4. Location of Well UNIT LETTER C 1980 FEET FROM THE West LINE AND 660 FEET FROM THE North LINE, SECTION 28 TOWNSHIP 18S RANGE 24E N.M.P.M.	10. Field and Pool, or Wildcat N. Antelope Sink
15. Elevation (Show whether DF, RT, CR, etc.) 3792.4 Gr.	12. County Eddy

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

13-3/8" set @ 225 cmt circl.  
8-5/8" set @ 1102 cmt circ.  
5 1/2" set @ 8540 500 sxs cmt

Perfs: 8231-8229  
8216-8209

Set CLBP @ 8150' with 35' cmt on top-~~xxx~~ Then fill hole with 9.5# mud  
Set 100' plug at 5 1/2" stub (approx. 6900') and tag  
set 100' plug @ 4950-5050'  
set 100' plug @ 3800-3900'  
set 100' plug @ 2120-2220'  
Set 100' plug across 8-5/8" shoe @ 1050-1150' and tag  
set 10 sx plug @ surface

If 5 1/2' is shot at higher depth then whatever depth will determine the remainder of plugs to be set in open hole

Plugging operation to begin as soon as approval is received on this report

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John Williams TITLE Agent DATE 3-13-78

APPROVED BY Mike Williams TITLE OIL AND GAS INSPECTOR DATE MAR 17 1978

CONDITIONS OF APPROVAL, IF ANY: \* as noted above

Notary Public in and for the State of New Mexico