Form 9–331	MY OU THE COMMERCEMED BY	C
Dec. 1973	ATTONITED STATES 10 NOV 13 1984	Budget Bureau No. 42-R142
	DEPARTMENT OF THE INTERIOR, C. D.	5. LEASE
	GEOLOGICAL SURVEY ARTESIA, OFFICE	N M - 14843 IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDF	RY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use thi	is form for proposals to drill or to deepen or plug back to a different Form $9-331-C$ for such proposals.)	Ballard Grayburg San Andres Ur 8. FARM OR LEASE NAME
1. oil	gas	Tract No. 20
	ywell <u>other X-Water Injection well</u> DF OPERATOR	
	rko Production Company	6 10. FIELD OR WILDCAT NAME
3. ADDRES	S OF OPERATOR	Loco Hills-Queen-Grayburg-San
P. 0.	Drawer 130, Artesia, New Mexico 88210	11. SEC., T., R., M., OR BLK. AND SURVEY O AREA
below.)	ON OF WELL (REPORT LOCATION CLEARLY. See space 17	17 - 18S - 29E
AT SUR		12. COUNTY OR PARISH 13. STATE
	AL DEPTH: Same	Eddy New Mexico
16. CHECK	APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT,	, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD 3509 ' GL
REQUEST FC TEST WATER	DR APPROVAL TO: SUBSEQUENT REPORT OF:	5507 62
FRACTURE T	REAT	
SHOOT OR A		
PULL OR AL		(NOTE: Report results of multiple completion or zon change on Form 9-330.)
MULTIPLE CO CHANGE ZON		
ABANDON*		
(other)	X - Change Injection Profile	
	BE PROPOSED OR COMPLETED OPERATIONS (Clearly state g estimated date of starting any proposed work. If well is d d and true vertical depths for all markers and zones pertinen	
measure	d and true vertical depths for all markers and zones pertinen	
 RUPU; GIH wi 	TOH with tubing and packer. The bit and clean out to PBTD of 2690';	rectionally drilled, give subsurface locations and it to this work.)*
 RUPU; GIH wi GIH wi chemic 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500#	TOH.
 RUPU; GIH wi GIH wi chemic regula 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500#	TOH. culate hole with fresh water and in accordance with NMOCD rules a
 RUPU; GIH wi GIH wi GIH wi chemic regula Return K-Trol 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# Itions. It o injection for a few days till injec. It reatment to change injection profile.	TOH. TOH. culate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do
 RUPU; GIH wi GIH wi GIH wi chemic regula Return K-Trol Place 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# itions. It o injection for a few days till injec. Iteatment to change injection profile. well on injection for appropriate time	TOH. TOH. culate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do
 RUPU; GIH wi GIH wi chemic regula Return K-Trol Place K-Trol 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. Ito injection for a few days till injec treatment to change injection profile. well on injection for appropriate time to PBTD of 2690'; GIH with packer: cir	TOH. TOH. culate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do
 RUPU; GIH wi GIH wi chemic regula Return K-Trol Place K-Trol Return 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# itions. It o injection for a few days till injec. Iteatment to change injection profile. well on injection for appropriate time	TOH. culate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing.
 RUPU; GIH wi GIH wi GIH wi chemic regula Return K-Trol Place K-Trol Return Note: 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. It o injection for a few days till injections. It o injection for a few days till injection profile. Well on injection for appropriate time to PBTD of 2690'; GIH with packer; cir well to injection. Will run injection profile after appro	TOH. TOH. culate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection.
 RUPU; GIH wi GIH wi GIH wi chemic regula Return K-Trol Place K-Trol Return <u>Note</u>: 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. It o injection for a few days till injections. It o injection for a few days till injection profile. Well on injection for appropriate time to PBTD of 2690'; GIH with packer; cir well to injection. Will run injection profile after appro-	TOH. TOH. culate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection.
 RUPU; GIH wi GIH wi GIH wi chemic regula Return K-Trol Place K-Trol Return <u>Note</u>: Subsurface Sa 18. hereby c 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. Ito injection for a few days till injec treatment to change injection profile. Well on injection for appropriate time to PBTD of 2690'; GIH with packer; cir Well to injection. Will run injection profile after appro- afety Valve: Manu. and Type	TOH. TOH. TOH. Toulate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection.
 RUPU; GIH wi GIH wi GIH wi chemic regula Return K-Trol Place K-Trol Return <u>Note</u>: Subsurface Sa 18. hereby c 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. Ito injection for a few days till injec treatment to change injection profile. Well on injection for appropriate time to PBTD of 2690'; GIH with packer; cir Well to injection. Will run injection profile after appro- afety Valve: Manu. and Type certify that the foregoing is true and correct TITLE Field Foreman	TOH. TOH. rculate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection. Set @ Ft n November 6, 1984
 RUPU; GIH wi GIH wi Chemic regula Return K-Trol Place K-Trol Return Subsurface Sa I hereby considered 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. Ito injection for a few days till injec treatment to change injection profile. Well on injection for appropriate time to PBTD of 2690'; GIH with packer; cir Well to injection. Will run injection profile after appro- afety Valve: Manu. and Type	TOH. TOH. rculate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection. Set @ Ft n November 6, 1984 re use)
 RUPU; GIH wi GIH wi Chemic regula Return K-Trol Place K-Trol Return Subsurface Sa I hereby considered 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. Ito injection for a few days till injections. Ito injection for a few days till injection profile. Well on injection for appropriate time Ito PBTD of 2690'; GIH with packer; cir Well to injection. Will run injection profile after appro- certify that the foregoing is true and correct TITLE Field Forema: (This space for Federal or State office CARLSEAD ALSON ALL IF ANY:	TOH. TOH. rculate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection. Set @ Ft n November 6, 1984 re use)
 RUPU; GIH wi GIH wi GIH wi Chemic regula Return K-Trol Place K-Trol Return Note: Subsurface Sa I hereby consistence SiGNED 110 APPROVED BY CONDITIONS OF 	TOH with tubing and packer. TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. Ito injection for a few days till injections. Ito injection for a few days till injection profile. Well on injection for appropriate time Ito PBTD of 2690'; GIH with packer; cir Well to injection. Will run injection profile after appro- certify that the foregoing is true and correct TITLE Field Forema: (This space for Federal or State office CARLSEAD ALSON ALL IF ANY:	TOH. TOH. rculate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection. Set @ Ft n November 6, 1984 re use)
 RUPU; GIH wi GIH wi GIH wi Chemic regula Return K-Trol Place K-Trol Return <u>Note</u>: Subsurface Sa I hereby consistence Signed <u>11</u> 	TITLE Field Foreman (This space for Federal or State offic A and true vertical depths for all markers and zones pertinen TOH with tubing and packer. Ith bit and clean out to PBTD of 2690'; Ith packer and plastic lined tubing; cir cal; set packer and test casing to 500# ations. Ito injection for a few days till injec treatment to change injection profile. Well on injection for appropriate time to PBTD of 2690'; GIH with packer; cir Well to injection. Will run injection profile after appro After Amarker and Type Cartispace for Federal or State offic F APPROVAL, IF ANY:	TOH. TOH. TOH. Toulate hole with fresh water and in accordance with NMOCD rules a tion rate stabilizes and then do then TOH with packer; clean out culate hole and test casing. priate water injection. Set @ Ft n November 6, 1984 Te use) DATE Ft