State of New Mexico Energy, Minerals and Natural Resources Department

DISTRICTI		
DISTRICT I	Hobbs, NM	88240

DISTRICT II P.O. Drawer DD, Artesia, NM \$8210

OIL CONSERVATION DIVISION P.O. Box 2088 Santa Fe, New Mexico 87504-2088

WELL API NO.		
·	 	
5. Indicate Type of Lease STATE X	FEE	

P.O. Drawer DD, Artesia, NM \$8210	STATE A FEE			
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM \$7410	6. State Oil & Gas Lease No. K-6259 & K-6458			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR F DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name			
1. Type of Well:				
OIL GAS WELL X OTHER	Dinkus Comm.			
2. Name of Operator AF	PR 07 '89 8. Well No.			
Bravo Operating Co. V	9. Pool same or Wildcat			
3. Address of Operator	O. C. O. Bidy Undes. Atoka (Gas)			
	ESIA, OFFICE			
4. Well Location	Line and 1980 Feet From The West Line			
Unit Letter K: 1980 Feet From The South				
Section 28 Township 18S Range	25E NMPM Eddy County			
Section 28 Township 185 Range 10. Elevation (Show whether DF, Range 10	KB, RT, GR, etc.)			
V/////////////////////////////////////	V/////////////////////////////////////			
Charle Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK				
	MMENCE DRILLING OPNS. PLUG AND ABANDONMENT			
PULL OR ALTER CASING CA	SING TEST AND CEMENT JOB			
— ·	HER:L			
VIII.611.	and inent dates including estimated date of starting any proposed			
12. Describe Proposed or Completed Operations (Clearly state all persinent details, and give work) SEE RULE 1103.	t has true to among a monominal and an			
1. Set CIBP @ 8590'±. Cap with 35' cement.				
2. Free point and shoot off casing (Est. 6400'±).				
3. Displace hole with Salt Gel Mud.				
4 Spot 25 sy plug @ 7555'.				
$\frac{1}{2}$ $\frac{1}$				
6. Spot 25 sx plug across 5½" csg stub. (50° in & 50° out). Tag this plug.				
7 7 75 75 71 71 71 7 7 7 7 7 7 7 7 7 7 7				

7. Spot 35 sx plug @ 5465'.

Spot 35 sx plug @ 42001. Spot 35 sx plug @ 2100'.

Spot 35 sx plug @ 1200'. Tag this plug.

Spot 35 sx plug @ 300'.

Spot 10 sx plug @ surface.

Clean location, cut off anchors, install dry hole marker. Make location ready for

inspection. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TYPE OR PRINT NAME

(Thus space for State Use) CONDITIONS OF AFFROVAL IF ANY

TELEPHONE NO.

_ DATE April 6, 1989

Plugging