

BILL GRESSET

ID 150 - Feb - 6' density
LC - came out of hole & hole
started coming in - Cracked
about 10' in front of sub-structure
all around rig.
I went out @ 10:40 & they had
put 8 truck loads of gravel -
in & loader was filling hole -
to move rig -