

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

015F
BF

OIL CONSERVATION DIVISION

DISTRICT I
P. O. Box 1980 Hobbs, NM 88240

P. O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P. O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

Well API NO.	30-015-22369
5. Indicate Type or Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	LOCO HILLS WELCH
8. Well No.	# 1
9. Pool name or Wildcat	LOCO HILLS BONE SPRING

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	2. Name of Operator Harvey E. Yates Company
3. Address of Operator P.O. Box 1933, Roswell, NM 88202 1-505-623-6601	
4. Well Location Unit Letter <u>D</u> : <u>480</u> Feet From The <u>NORTH</u> Line and <u>500</u> Feet From The <u>WEST</u> Line Section <u>9</u> Township <u>18S</u> Range <u>29E</u> NMPM <u>EDDY</u> County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3516' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103

NOTIFY OCD II -ARTESIA 24 HOURS PRIOR TO COMMENCEMENT

SET CIBP @ 6175' PLUS 35' CMT.

FREE POINT CSG & CUT (EST. 5500' REC.)

POOH LAYING DOWN CASING.

100' PLUG (50' IN & OUT) @ CUT STUB @ APPROX. 5500' & TAG

100' PLUG @ 2950' & TAG

100' PLUG @ 450' Perforate 8 3/8" casing @ 450' Squeeze 100' cement Plug inside & outside

CUT OFF WH 5 5/8" casing. Tag

PUMP 50' SURFACE PLUG

INSTALL DRY HOLE MARKER.

BACKFILL PIT & CLEAN LOCATION.

ARTESIA OCD II 1-505-748-1283



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ray F. Nokes TITLE PROD. MGR. / ENGINEER. Date 11/9/99
TYPE OR PRINT NAME RAY F. NOKES TELEPHONE NO. 1-505-623-6601
(This space for State use)

Approved by mine stillfield Title Field Rep. II Date 11/14/99
Conditions of approval, if any:

* Brine gel between all cement Plugs.